

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

or corners in

Dickinson	Located In:	Corner Code #
(County)		
ELCH TOWNSHIP		
Public Land Survey	T R	
	T R	
	T R	
Property Controlling	S 24 T 42N R 29W	12
Section	S 24 T 42N R 29W	13
	S T R	
Miscellaneous	S T R	
Property in Sec.	S T R	
Lot No. , Recorded Plat		
Private Claims		

Jeremy J. Pipp, in a field survey on 7/01/2014 do hereby state  
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2  
above were in conformance with regulations and rules therefore as required in the current manual of survey  
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of  
Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with  
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,  
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded  
in this certificate.

1. Description of original monument and accessories and/or subsequent restoration:

(12) Center-South One-Sixteenth corner of Section 24. Not set in original survey, no evidence of  
subsequent establishment.

(13) Southeast One-Sixteenth corner of Section 24. Not set in original survey, no evidence of  
subsequent establishment.

2. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(12) Corner position established mid-point and on-line between the Center One-Quarter corner and  
the South One-Quarter corner of Section 24.

(13) Corner position established at the intersection of the South and East One-Sixteenth lines of  
Section 24. Monument is at north edge of E-W rock out crop; +/- 100 feet North of vertical face.

3. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(12) DNR monument  
9" Cedar N58E 11.84' (1/16S,BT)  
12" Cedar S25E 14.22' (1/16S,BT)  
3" Ash S59W 8.41' (1/16S,BT)  
7" Ash N34W 11.78' (1/16S,BT)

All trees are blazed, scribed, and  
painted. Measurements are to nail in  
side of tree, bearings are magnetic.

Signed by  
Surveyor's Michigan License No. 50447

For the Michigan Department of Natural Resources, Forest Resource Division

(13) DNR monument  
5" Maple N06E 16.36' (1/16S,BT)  
7" Maple N87E 9.12' (1/16S,BT)  
6" Maple S19W 17.16' (1/16S,BT)  
6" Maple N86W 13.62' (1/16S,BT)  
All trees are blazed, scribed, and  
painted. Measurements are to nail in  
side of tree, bearings are magnetic.



July 15, 2014