

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

or corners in

Dickinson	Located In:	Corner Code #
(County)		
ELCH TOWNSHIP		
Public Land Survey	T R	
	T R	
	T R	
Property Controlling	S 29 T 42N R 29W	04
Section	S 29 T 42N R 29W	08
	S T R	
Miscellaneous	S T R	
Property in Sec.	S T R	
Lot No. , Recorded Plat		
Private Claims		

6/30/2014  
Jeremy J. Pipp, in a field survey on 6/30/2014 do hereby state  
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2  
above were in conformance with regulations and rules therefore as required in the current manual of survey  
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of  
Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with  
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,  
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded  
in this certificate.

1. Description of original monument and accessories and/or subsequent restoration:

(04) Northwest One-Sixteenth corner of Section 29. Not set in original survey. Found Angle Iron  
3.5 foot high N16W +/-32 feet from calculated position.

(08) Center-West One-Sixteenth corner of Section 29. Not set in original survey. Found 1 1/4" pipe  
2.5 feet high S35E 28.20 feet from calculated position.

3. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(04) Corner position established at the intersection of the North and West One-Sixteenth lines of  
Section 29. Found Angle Iron not accepted.

(08) Corner position established mid-point and on-line between the Center One-Quarter corner and  
the West One-Quarter corner of Section 29. Found Pipe not accepted.

2. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(04) DNR monument  
12" W. Pine N68E 10.88' (1/16S,BT)  
5" W. Pine S55E 19.32' (1/16S,BT)  
11" W. Pine S48W 50.18' (1/16S,BT)  
16" W. Pine N75W 36.96' (1/16S,BT)

All trees are blazed, scribed, and  
painted. Measurements are to nail in  
side of tree, bearings are magnetic.

Signed by  
Surveyor's Michigan License No. 50447

For the Michigan Department of Natural Resources Forest Resource Division

(08) DNR monument  
15" Spruce N55E 7.52' (1/16S,BT)  
8" Cedar S29E 15.43' (1/16S,BT)  
8" Cedar S16W 18.90' (1/16S,BT)  
6" Cedar N56W 20.33' (1/16S,BT)  
All trees are blazed, scribed, and  
painted. Measurements are to nail in  
side of tree, bearings are magnetic.



Register of Deeds Stamp & File Number												
	A	B	C	D	E	F	G	H	I	J	K	L
1												
2	6			5		4		3		2		1
3												
4	7			8		9		10		11		12
5												
6	18			17		16		15		14		13
7												
8	19			20		21		22		23		24
9												
10	30			29		28		27		26		25
11												
12	31			32		33		34		35		36
13												