

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

or corners in

Dickinson (County) Located In: Corner Code #
Public Land Survey T 42N R 29W F07
T 42N R 29W G07
Property Controlling S T R
Section S T R
Miscellaneous S T R
Property in Sec. S T R

Lot No. Recorded Plat
Private Claims

Jeremy J. Pipp, in a field survey on 6/24/2014 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
structions of the United States Department of the Interior, Bureau of Land Management or by a decree of
Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

3. Description of original monument and accessories and/or subsequent restoration:

(F07) Quarter corner common to Sections 16 and 21. 1849: John Burt, DS. Set Y. Birch post
witnessed by: Y. Birch 8 N23W 25 links (16.50'), W. Pine 30 S35E 14 links (9.24'). 1977:
Michigan DNR (Arthur Enger, PS#13581) Set 1" pipe with 3 3/4" Aluminum cap by proportionate method
witnessed by Sugar Maple 7 S69W 14.7', Sugar Maple 5 N51E 13.7'.

(G07) Corner common to Sections 15, 16, 21, and 22. 1849: John Burt, DS. Set Cedar post witnessed
by: Y. Birch 10 S55E 18 links (11.88'), Cedar 14 N12W 63 links (41.58'). 1977: Michigan DNR
(Arthur Enger, PS#13581) Set 1" pipe with 3 3/4" Aluminum cap from probable OBT witnessed by Red
Maple 7 N70E 46.5'; Elm 22 N32W 4.3'.

4. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(F07) Accepted found MDNR Monument, and Two NBT Witnesses (both living). Position is accepted as a
careful and faithful REESTABLISHMENT of the position of the original corner.

(G07) Accepted found MDNR Monument, trace remains of probable OBT's (per 1976 MDNR), and one NBT
Witness (Maple living, Elm is a mound). Position is accepted as a careful and faithful PERPETUATION
of the position of the original corner.

5. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(F07) DNR monument (G07) DNR monument
EX 7" Maple N60E 14.02' (1/4S,NBT) 16" Spruce N16E 14.98' (S 15,NBT)
10" Maple S32E 22.63' (1/4S,NBT) EX 15" Maple N72E 46.78' (S 15,NBT)
EX 14" Maple S65W 14.88' (1/4S,NBT) 9" Spruce S71E 35.69' (S 22,NBT)
5" Maple N12W 31.91' (1/4S,NBT) 17" Spruce N30W 17.23' (S 16,NBT)
All trees are blazed, scribed, painted, and signed. Measurements are to nail in
side of tree, bearings are magnetic. A
Carsonite rail was set East 1.5 feet.
Signed by Jeremy Pipp Date July 15, 2014
Surveyor's Michigan License No. 50447

For the Michigan Department of Natural Resources



Table with 13 rows and 13 columns (A-M) for Register of Deeds Stamp & File Number. Contains numerical data for each cell.