

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

or corners in

Dickinson	Located In:	Corner Code #
(County)		
ELCH TOWNSHIP		
Public Land Survey	T 42N R 29W	I10
	T 42N R 29W	D11
	T R	
Property Controlling	S T R	
Section	S T R	
	S T R	
Miscellaneous	S T R	
Property in Sec.	S T R	

Lot No. , Recorded Plat  
Private Claims

Jeremy J. Pipp, in a field survey on 6/30/2014 do hereby state

that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

3. Description of original monument and accessories and/or subsequent restoration:

I10) Quarter corner common to Sections 26 and 27. 1849: John Burt, DS. Set cedar post, no witnesses listed. 2005: Michigan DNR (Paul Bressette, PS#37270) Set 1" pipe with 3 3/4" Aluminum cap by proportionate method witnessed by 09" Spruce N54E 8.4' (1/4S,NBT), 10" Basswood S36E 39.5' (1/4S,NBT), 08" Sugar S81W 46.7' (1/4S,NBT), 12" Spruce N36W 12.85' (1/4S,NBT).

D11) Quarter corner common to Sections 29 and 32. 1849: John Burt, DS. Set quarter section post witnessed by Black Ash 16 S68E 58 links (38.28'), Cedar 9 N40W 23 links (15.84'). 2000: Coleman Engineering Company (James H. Moore, PS#28423) Found 1" pipe with union on top and added witnesses 8" Yellow Birch N38E 20.17', 12" Yellow Birch S72E 34.10', 10" Maple S39W 14.52', 10" Maple West 8.28'.

4. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(I10) Accepted found MDNR Monument and Four NBT Witnesses (all living). Position is accepted as a careful and faithful REESTABLISHMENT of the position of the original corner.

(D11) Accepted found pipe and Four NBT Witnesses (all living). Position is accepted as a careful and faithful REESTABLISHMENT of the position of the original corner. Replaced existing pipe with MDNR aluminum capped monument in a karn of stones and reset pipe with union as a guard pipe South 1.0'. Also existing NW NBT was noted as a Maple in October 2000, is actually a Basswood as seen at leaf on 6/30/14.

5. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(I10) DNR monument  
EX 09" Spruce N54E 8.39' (1/4S,NBT)  
EX 10" Basswood S36E 39.48' (1/4S,NBT)  
EX 08" Sugar S81W 46.70' (1/4S,NBT)  
EX 12" Spruce N36W 12.85' (1/4S,NBT)

All trees are blazed, scribed and painted. Measurements are to nail in side of tree, bearings are magnetic. A Carsonite rail was set North 1.5 feet.

Signed by Surveyor's Michigan License No. 50447

For the Michigan Department of Natural Resources

(D11) DNR monument  
EX 08" Y. Birch N43E 19.96' ( - , - )  
EX 14" Y. Birch S70E 36.27' ( - , - )  
EX 10" Maple S42W 14.65' ( - , - )  
EX 11" Basswood N85W 8.34' ( - , - )

All trees are blazed, scribed and painted. Measurements are to nail in side of tree, bearings are magnetic. A Carsonite rail was set North 1.5 feet.

Signed by Surveyor's Michigan License No. 50447

For the Michigan Department of Natural Resources



Register of Deeds Stamp & File Number

A	B	C	D	E	F	G	H	I	J	K	L	M
1												
2	6		5		4		3		2		1	
3												
4	7		8		9		10		11		12	
5												
6	18		17		16		15		14		13	
7												
8	19		20		21		22		23		24	
9												
10	30		29		28		27		26		25	
11												
12	31		32		33		34		35		36	
13												