

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

corners in

Dickinson Located In: Corner Code #
(County)
T 42N R 29W J09
Public Land Survey
Property Controlling Section
Miscellaneous Property in Sec.

Lot No. Recorded Plat
Private Claims

Jeremy J. Pipp, in a field survey on 6/26/2014 do hereby state
at under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
structions of the United States Department of the Interior, Bureau of Land Management or by a decree of
Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
e rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
-established, monumented, recovered, found as expressed below:

OTE: Not more than 2 corners, all in the same town and range, may be recorded
n this certificate.

Description of original monument and accessories and/or subsequent restoration:

J09) Quarter corner common to Sections 23 and 26. Original corner established in 1849 by
ohn Burt as follows: "40.00 Set Hemlock qr. Sect. post. Y. Birch 9 S57W 62, Y. Birch 12
152E 69". 1995: Michigan DNR (Steve Szyszkoski, PS#33986) Placed a 1"IDx24" iron pipe,
driven into the rocky crevices on the north side of a ridge, capped with a yellow plastic
cap "MICH DNR LS 33986". Blazed and scribed the following: 9" Sugar S71W 28.8' "1/4S NBT"
1" Sugar N55W 30.2' (slope)"1/4S NBT" 5" Sugar N82E 25.5' "1/4S NBT" 6" Sugar with
ocation poster S23E 5.1' mrkd "1/4S NBT".

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

J09) Accepted found 3/4" pipe and Four NBT Witnesses (three living, one NE standing
lead). Position is accepted as a careful and faithful REESTABLISHMENT of the position of
the original corner. SET 1" pipe with aluminum MDNR cap over said 3/4" pipe and secured
position in karn of stones.

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

J09) DNR monument
7" Maple N75E 24.64' (1/4S,NBT)
EX 7" Maple S25E 5.32' (1/4S,NBT)
EX 11" Maple S77W 28.71' (1/4S,NBT)
EX 12" Maple N50W 29.00' (1/4S,NBT)
All trees are blazed, scribed, painted,
and signed. Measurements are to nail in
side of tree, bearings are magnetic. A
Carsonite rail was set South 2.5 feet.

Signed by
Surveyor's Michigan License No. 50447



July 15, 2014

For the Michigan Department of Natural Resources, Forest Resources Division