

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD

T. 42 N.R. 29 W


Dickinson COUNTY

DESCRIPTION OF CORNER 1/4 Corner for Secs. 5/8

CORNER MONUMENT 1" Iron Pipe with 4" Aluminum Cap

DATE MONUMENT PLACED AND WITNESSED 10/22/65

WITNESSES TO CORNER..... 9" Cedar (1/4S NBT), N 85° W, 34 Lks.



7" Cedar (1/4S NBT), S 04° E, 32 Lks.

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This Corner was placed midway and on line between Section Corners.

No original evidence found. Old E-W blazes near.

SURVEYOR'S SEAL

SIGNED Frank J. Bray DATE 11/15/1965  
REGISTERED LAND SURVEYOR