

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Dickinson	Located In:	Corner Code #
(County)		
West Branch Township		
1. Public Land Survey	T 43N R 27W	D08
	T R	
	T R	
2. Property Controlling in Section	S T R	
	S 20 T 43N R 27W	16
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. , Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5			4		3		2		1	
3													
4	7		8			9		10		11		12	
5													
6	10		17			16		15		14		13	
7													
8	19					21		22		23		24	
9													
10	30		29			28		27		26		25	
11													
12	31		32			33		34		35		36	
13													

I, Jeremy J. Pipp, in a field survey on 8/22/2012AD do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(D08) Center One-Quarter Corner of Section 20. Not set in original survey.

(16) East One-Sixteenth corner common to Sections 20 and 29. Not set in original survey, no evidence of subsequent establishment.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(D08) Corner position established at the intersection of the North-South and East-West One-Quarter lines of Section 20. Found Two pipes (1/2" & 1 1/4") N54W +/-15 feet from calculated position, not accepted.

(16) Corner position established mid-point and on-line between the South One-Quarter corner and the Southeast corner of Section 20. Found 'U' Shaped rail 4 feet high S56W +/-22 feet from calculated position, not accepted.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(D08) DNR monument
6" Maple N24E 23.29' (1/4S,BT)
5" Ash N87E 34.00' (1/4S,BT)
5" Balsam S46E 24.50' (1/4S,BT)
10" Cherry S35W 36.05' (1/4S,BT)

All trees are blazed, scribed, and painted. Measurements are to nail in side of tree, bearings are magnetic.

(16) DNR monument
9" Cedar N60E 4.62' (1/16S,BT)
7" Cedar S09E 5.48' (1/16S,BT)
11" Cedar S51E 14.58' (1/16S,BT)
11" Cedar N69W 27.35' (1/16S,BT)

All trees are blazed, scribed, and painted. Measurements are to nail in side of tree, bearings are magnetic.

Signed by Jeremy J. Pipp
Surveyor's Michigan License No. 50447

For the Michigan Department of Natural Resources, Original and Facsimiles



Date August 29, 2012

20129

20127

Revised May 14, 1975
Revised Jan., 1983
Revised Oct., 1995