

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Dickinson (County) Located In: Corner Code #
WEST BRANCH TOWNSHIP
1. Public Land Survey
2. Property Controlling in Section
3. Miscellaneous Property in Sec.
4. Lot No. Recorded Plat
5. Private Claims

6/17/2013AD
Jeremy J. Pipp, in a field survey on 6/17/2013AD do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(04) Northwest One-Sixteenth corner of Section 30. Not set in original survey, no
evidence of subsequent establishment.

(05) Center-North One-Sixteenth corner of Section 30. Not set in original survey.
Found Iron Pin with bolt top, not of record, S75W 4.95 feet from calculated position.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(04) Corner position established at the intersection of the North and West One-
Sixteenth lines of Section 30.

(05) Corner position established mid-point and on-line between the Center One-Quarter
corner and the North One-Quarter corner of Section 30.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(04) DNR monument
16" Cherry N22E 39.96' (1/16S,BT)
18" Cherry N71E 37.58' (1/16S,BT)
Fence Post S05E 11.70' (1/16S,BT)
13" Cherry N83W 34.83' (1/16S,BT)
All trees are blazed, scribed, and
painted. Measurements are to nail in
side of tree, bearings are magnetic.
(05) DNR monument
8" Spruce N50E 22.82' (1/16S,BT)
15" Cedar S25E 47.17' (1/16S,BT)
13" Cedar S53W 15.35' (1/16S,BT)
13" Spruce N64W 8.27' (1/16S,BT)
All trees are blazed, scribed, and
painted. Measurements are to nail in
side of tree, bearings are magnetic.

Signed by Jeremy J. Pipp Date August 08, 2013
Surveyor's Michigan License No. 50447

For the Michigan Department of Natural Resources, Forest Resource Division



Table with 13 rows and 13 columns (A-M) for Register of Deeds Stamp & File Number. Contains numerical data for each cell.