LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Dickinson	_ Located in:	Corner Code #										
(County) WEST BRANCH TOWNSHIP 1. Public Land Survey	TR TR											
2. Property Controlling in Section	S 19 T 43N R 27W S 19 T 43N R 27W S T R	08										
3. Miscellaneous Property in Sec.	S T R S T R			leais	ter of I)eeds	Stam	nn & F	File N	umb	er	
4. Lot No, Red	corded Plat				C D	E F	G	H	I J		L	
Private Claims			1			\Box		\top		T	Ť	
	6/10/201	3AD	2	6—	-5-	+-1	1	-3 I	 2	<u>'</u>	-1	
, Jeremy J. Pipp , ii	n a field survey on 6/11/201	3AD do hereby state	3	1				_	1-1	\dashv	\dashv	_
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2			2 4	7—	B-	+- :	'	-10	†¥	1	—13 —13	2
above were in conformance with regulations and rules therefore as required in the current manual of survey			, 5 -	╫			-	+	+	-	\dashv	
nstructions of the United States Department of the Interior, Bureau of Land Management or by a decree of			f 6	10	17-	1	5	-15	 1	4	1	. —
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with				┼~		+		+	+		-	
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,			8 0	19—	_20_	- 2	3	-22-	 2	3-	24	!
'e-established, monumented, recov	ered, found as expressed below:		9	-		\bot			\sqcup		_	
			10] 30—	_29_		в.	_27 <u>_</u> _	 2	6		<u>5</u> —
NOTE: Not more than 2 corners, all in the same town and range, may be recorded			11	1					$oxed{\Box}$			
on this certificate.			12	j 31—	32_		\perp	_34_				<u>. </u>
			13					Ĺ			Ĩ	
A. Description of original monument and accessories and/or subsequent restoration:												

- (08) Center-West One-Sixteenth corner of Section 19. Not set in original survey, no evidence of subsequent establishment.
- (11) Southwest One-Sixteenth corner of Section 19. Not set in original survey, no evidence of subsequent establishment.
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- (08) Corner position established proportionate measurement and on-line between the Center One-Quarter corner and the West One-Quarter corner of Section 19.
- (11) Corner position established at the intersection of the South and West One-Sixteenth lines of Section 19.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(11)DNR monument (08) PK NAIL w/DNR Tag in CL of CO. RD 9" B. Spruce N36E 18.33' (1/16S,BT) Curve/40mph sign S69E 82.6' (- , -) 6" B. Spruce S09E S44W 56.6' (1/16S,BT) NO1W 45.74' (- , -13" Poplar 5" B. Spruce S46W Fence Post (- , -) 9" B. Spruce N73W All trees are blazed, scribed, and All trees are blazed, scribed, and painted of Measurements are to nail in side of tree, bearings are magnetic. painted. Measurements are to nail in side of tree, bearings are magnetic.

Surveyor's Michigan License No.

For the Michigan Department of Natural Resource

JEREMYDate PTPP
PROFESSIONAL
TEST RESULT FORM APERITED BY MICHIGA

August 08, 2013

4.85' (1/16S,BT)

5.75' (1/16\$,BT)

4.52' (1/16S,BT)

50447

20218

Signed by

Revised May 14, 1975 Revised Jan., 1983 OFESSION Rervised Oct., 1995