

2

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. ⁴³ NR. 27 W.

Dickinson

COUNTY

DESCRIPTION OF CORNER Section corner common to sections 3, 4, 9 and 10

DESCRIPTION OF CORNER MONUMENT 1" pipe with 4" brass cap

WITNESSES TO CORNER Black spruce 6" S 89 E 26 1/2 links, marked S10 NBT

Tamarack 7" N 22 W 25 links, marked S 4 NBT

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR
RESTORED.

This corner was replaced from two original cedar bearing trees, both down. One in good condition with scribe marks plain. One in poor condition but found scribe marks in overgrowth scar tissue. Old wood post near by.

Corner was found while cruising timber in this area.

Corner was placed and witnessed on 21 April 1958 with Norman J. Karsten.

SURVEYORS SEAL

Henry S. Peterson
SIGNED Henry S. Peterson
REGISTERED LAND SURVEYOR

DATE 4/21/58