

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Dickinson (County) Located In: Corner Code #
WEST BRANCH TOWNSHIP
1. Public Land Survey
2. Property Controlling Section
3. Miscellaneous Property in Sec.

4. Lot No. , Recorded Plat
5. Private Claims

6/18/2013AD
6/19/2013AD
Jeremy J. Pipp, in a field survey on do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(08) Center-West One-Sixteenth corner of Section 25. Not set in original survey, no evidence of subsequent establishment.
(01) West One-Sixteenth corner common to Sections 23 and 26. Not set in original survey. Found 'T' Iron S11W 25.7' from calculated position.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(08) Corner position established mid-point and on-line between the Center One-Quarter corner and the West One-Quarter corner of Section 25. Corner falls 5 feet west of N-S fenceline & +/- 10 feet south of woods road.
(01) Corner position established mid-point and on-line between the North One-Quarter corner and the Northwest corner of Section 26. Found 'T Iron not accepted. "

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(08) DNR monument
5" Ironwood N25E 19.37' (1/16S,BT)
10" Maple S40E 17.08' (1/16S,BT)
8" Maple S05W 10.46' (1/16S,BT)
5" Maple N87W 19.03' (1/16S,BT)
All trees are blazed, scribed, painted, and signed. Measurements are to nail in side of tree, bearings are magnetic.
(01) DNR monument
11" W. Pine N37E 33.02' (1/16S,BT)
4" Ironwood S32E 19.04' (1/16S,BT)
8" Oak S63W 28.34' (1/16S,BT)
7" Maple N30W 9.45' (1/16S,BT)
All trees are blazed, scribed, painted, and signed. Measurements are to nail in side of tree, bearings are magnetic.

Signed by
Surveyor's Michigan License No. 50447



Date August 08, 2013

Register of Deeds Stamp & File Number

Table with 13 rows and 13 columns (A-M) for Register of Deeds Stamp & File Number.