

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Dickinson (County) Located In: Corner Code #
WEST BRANCH TOWNSHIP
1. Public Land Survey
2. Property Controlling in Section
3. Miscellaneous Property in Sec.
4. Lot No. , Recorded Plat
5. Private Claims

6/18/2013AD
Jeremy J. Pipp, in a field survey on 6/18/2013AD do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(09) Center-East One-Sixteenth corner of Section 25. Not set in original survey. Found
1 1/4" Iron Pipe N19W 10.27 feet from calculated position, not of record.

(12) Center-South One-Sixteenth corner of Section 25. Not set in original survey, no
evidence of subsequent establishment.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(09) Corner position established mid-point and on-line between the Center One-Quarter
corner and the East One-Quarter corner of Section 25. Found pipe not accepted

(12) Corner position established mid-point and on-line between the Center One-Quarter
corner and the South One-Quarter corner of Section 25. Monument falls +/- 15 feet north
of farm access road.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(09) DNR monument
3" Maple S01E 4.71' (1/16S,BT)
10" R. Pine S50W 60.45' (1/16S,BT)
12" Cherry N73W 17.37' (1/16S,BT) 1
1/4"Iron Pipe N19W 10.27' (- , -) All
trees are blazed, scribed, painted, and
signed. Measurements are to nail in side
of tree, bearings are magnetic.

(12) DNR monument
12" Cherry N01E 34.21' (1/16S,BT)
4" Ironwood N49E 12.48' (1/16S,BT)
8" Ironwood S83E 19.31' (1/16S,BT)
5" Ironwood N21W 23.10' (1/16S,BT)
All trees are blazed, scribed, painted,
and signed. Measurements are to nail in
side of tree, bearings are magnetic.

Signed by [Signature]
Surveyor's Michigan License No. 50447



August 08, 2013

For the Michigan Department of Natural Resources, Forest Resource Division

Register of Deeds Stamp & File Number

Table with 13 rows and 13 columns (A-M) for Register of Deeds Stamp & File Number.