

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Dickinson	Located In:	Corner Code #
(County)		
WEST BRANCH TOWNSHIP		
1. Public Land Survey	T 43N R 28W	L10
	T R	
	T R	
2. Property Controlling in Section	S T R	
	S 25 T 43N R 28W	05
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. , Recorded Plat		
5. Private Claims		

I, Jeremy J. Pipp, in a field survey on 6/18/2013AD do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(L10) Center One-Quarter Corner of Section 25. Not set in original survey, no evidence of subsequent establishment.

(05) Center-North One-Sixteenth corner of Section 25. Not set in original survey, no evidence of subsequent establishment.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(L10) Corner position established at the intersection of the North-South and East-West One-Quarter lines of Section 25.

(05) Corner position established mid-point and on-line between the Center One-Quarter corner and the North One-Quarter corner of Section 25.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(L10)	DNR monument	(05)	DNR monument
13" Maple	N49E 20.80' (1/4S,BT)	13" Spruce	N06E 7.72' (1/16S,BT)
13" Maple	S26E 14.50' (1/4S,BT)	12" Cedar	S41E 18.94' (1/16S,BT)
10" Maple	S69W 8.24' (1/4S,BT)	10" Cedar	S81W 11.66' (1/16S,BT)
8" Maple	N20W 3.76' (1/4S,BT)	10" Cedar	N48W 26.16' (1/16S,BT)

All trees are blazed, scribed, and painted. Measurements are to nail in side of tree, bearings are magnetic.

Signed by Jeremy J. Pipp Date August 08, 2013
Surveyor's Michigan License No. 50447

For the Michigan Department of Natural Resources, Forest Reserve Division

