

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

corners in

Dickinson (County) Located In: Corner Code #
Public Land Survey
Property Controlling Section
Miscellaneous Property in Sec.

Lot No. Recorded Plat
Private Claims

Jeremy J. Pipp, in a field survey on 6/05/2014 do hereby state
at under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
structions of the United States Department of the Interior, Bureau of Land Management or by a decree of
Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
e rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
-established, monumented, recovered, found as expressed below:

OTE: Not more than 2 corners, all in the same town and range, may be recorded
n this certificate.

Description of original monument and accessories and/or subsequent restoration:

Prop Corner West of 14) Property Corner 2.5 Chains West of South One-Sixteenth corner common to
ections 20 and 21. 1964: Michigan DNR (Billy Buckler PS#8887) Set 1" pipe with 4" Aluminum cap
itnessed by 24" W. Pine Stump N13E 45 links (29.70), 8" W. Birch N83W 36.5 links (24.09'). 1993:
ichigan DNR (Steve Szyszkoski PS#33986) Found MDNR Monument witnessed by 6" R. Pine N34E 15.20',
" W. Pine N88E 10.62', 6" W. Pine S22W 27.45'.

Prop Corner West of E09) Property Corner 2.5 Chains West of Section corner common to Sections 20,
1, 28, and 29. 1964: Michigan DNR (Billy Buckler PS#8887) Set 1" pipe with 4" Aluminum cap
itnessed by 8" Maple S65W 73 links (48.18'), 7" W. Birch North 2.5 links (1.65'). 1993: Michigan
DNR (Steve Szyszkoski PS#33986) Found MDNR Monument witnessed by 4" Sugar S14E 7.73', 6" Sugar N67E
9.27'.

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Prop Corner West of 14) Accepted found MDNR Monument and Four NBT's (2 living, 2 standing dead).

Prop Corner West of E09) Accepted found MDNR Monument and Four BT's/NBT's (3 living, 1 standing
lead).

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(Prop Corner West of 14) DNR monument
EX 12" R. Pine N33E 15.27' (X,NBT)
3" W. Pine N84E 46.20' (X,NBT)
EX 7" W. Pine S23W 27.44' (X,NBT)
3" Maple N67W 20.50' (X,NBT)

All trees are blazed, scribed, and
painted. Measurements are to nail in
side of tree, bearings are magnetic.

Signed by
Surveyor's Michigan License No. 50447

For the Michigan Department of Natural Resources

(Prop Corner West of E09) DNR monument
EX 11" Maple N68E 19.18' (X,NBT)
EX 7" Maple S13E 7.76' (X,NBT)
5" Maple S46W 8.57' (X,NBT)
7" W. Birch N43W 18.96' (X,NBT)

All trees are blazed, scribed, and
painted. Measurements are to nail in
side of tree, bearings are magnetic.

JEREMY PIPP Date July 9, 2014

PROFESSIONAL SURVEYOR
50447

Table with 13 rows and 13 columns (A-M). Contains numbers 1-36 and a small diagram of a corner point.