

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

ir corners in

Dickinson
(County)
LCH TOWNSHIP
Public Land Survey
Property Controlling Section
Miscellaneous Property in Sec.

Lot No. , Recorded Plat
Private Claims

6/04/2014
Jeremy J. Pipp, in a field survey on 6/04/2014 do hereby state
at under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
structions of the United States Department of the Interior, Bureau of Land Management or by a decree of
Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
e rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
-established, monumented, recovered, found as expressed below:

OTE: Not more than 2 corners, all in the same town and range, may be recorded
n this certificate.

Description of original monument and accessories and/or subsequent restoration:

07) North One-Sixteenth corner common to Sections 29 and 30. Not set in original survey, no
vidence of subsequent establishment.

09) Center-East One-Sixteenth corner of Section 30. Not set in original survey, no evidence of
ubsequent establishment.

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

07) Corner position established mid-point and on-line between the East One-Quarter corner and the
northeast corner of Section 30.

09) Corner position established mid-point and on-line between the Center One-Quarter corner and
the East One-Quarter corner of Section 30. Monument surrounded by karn of stones.

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

07) DNR monument
7" Balsam N36E 11.66' (1/16S,BT)
4" Poplar S41E 6.63' (1/16S,BT)
4" W. Pine S43W 21.41' (1/16S,BT)
6" Poplar N57W 10.35' (1/16S,BT)
All trees are blazed, scribed, and
painted. Measurements are to nail in
side of tree, bearings are magnetic.

Signed by
Surveyor's Michigan License No. 80447

For the Michigan Department of Natural Resources Forest Resource Division

09) DNR monument
10" Maple N13E 33.12' (1/16S,BT)
8" Cedar S54E 33.37' (1/16S,BT)
7" Maple S43W 23.40' (1/16S,BT)
5" Maple N50W 13.81' (1/16S,BT)
All trees are blazed, scribed, and
painted. Measurements are to nail in
side of tree, bearings are magnetic.



July 9, 2014

Register of Deeds Stamp & File Number

Table with 13 rows and 13 columns (A-M) for recording deed stamps and file numbers.