

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Dickinson
(County)

Located In:

Corner Code #

FELCH TOWNSHIP

1. Public Land Survey

2. Property Controlling in Section

3. Miscellaneous Property in Sec.

4. Lot No. , Recorded Plat

5. Private Claims

T 43N R 28W

T

T

T

S 20 T 43N R 28W

S

S

S

T

T

T

T

B10

13

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6			5		4		3		2		1	
3													
4	7			8		9		10		11		12	
5													
6	18			17		16		15		14		13	
7													
8	19			20		21		22		23		24	
9													
10	2			29		28		27		26		25	
11													
12	31			32		33		34		35		36	
13													

6/09/2014
6/05/2014
Jeremy J. Pipp, in a field survey on do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(B10) Center One-Quarter Corner of Section 30. Not set in original survey, no evidence of subsequent establishment.

(13) Southeast One-Sixteenth corner of Section 20. Not set in original survey, no evidence of subsequent establishment.

3. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(B10) Corner position established at the intersection of the North-South and East-West One-Quarter lines of Section 30.

(13) Corner position established at the intersection of the South and East One-Sixteenth lines of Section 20.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(B10) DNR monument
3" Spruce N67E 7.68' (1/4S,BT)
10" Maple S29E 28.16' (1/4S,BT)
3" W. Birch S17W 19.63' (1/4S,BT)
13" W. Birch N49W 26.05' (1/4S,BT)

All trees are blazed, scribed, and painted. Measurements are to nail in side of tree, bearings are magnetic.

Signed by
Surveyor's Michigan License No. 50447

For the Michigan Department of Natural Resources, Forest Resources Division



(13) DNR monument
9" Maple N55E 26.93' (1/16S,BT)
5" Maple S17E 27.13' (1/16S,BT)
21" R. Pine S48W 32.27' (1/16S,BT)
9" Maple N37W 6.98' (1/16S,BT)
All trees are blazed, scribed, and painted. Measurements are to nail in side of tree, bearings are magnetic.

Date July 15, 2014

20355

20352