

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Dickinson

(County)

Felch Twp.

1. Public Land Survey

Located In:

Corner Code #

T 43NR 28W

C-11

T R

C-12

T R

T R

T R

T R

T R

T R

T R

2. Property Controlling
in Section

S

T R

3. Miscellaneous

S

T R

Property in Sec.

S

T R

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

I, Robert F. Perkins, in a field survey on Sept. 3, 1998 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

C-11 Corner Common to Sections 29-30-31-32
Post by John Burt, D.S. 1850
Original Bearing Trees
Cedar 14" S31°E 24 Lk.
Cedar 14" N72°W 25 Lk.

C-12 $\frac{1}{2}$ Corner Common to Section 31 and 32
Post by John Burt, D.S. 1850
Original Bearing Trees
Sugar 12" S9°E 35 Lk.
W.Pine 24" N33°W 43 Lk.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

C-11 11-2-1951 D.C. DeLaMater, RLS placed
1" Iron Pipe D.N.R. Monument from
2 Original BT's and made New BT:
Spruce 8" N55°W 23 Lk.
Refer to Old Corner Report #166

C-12 No Evidence of Original Corner
or its Accessories Found.
Location falls in Cut-over Highland
and was Subject to Forest Fires.

ACCEPTED BY THE DICKINSON COUNTY
SURVEY PEER GROUP AS THE OFFICIAL
CORNER UNDER MICHIGAN PUBLIC ACT
345 OF 1990 AT A MEETING HELD ON
12-7-98

RFP
COUNTY REPRESENTATIVE


C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

C-11 Found D.N.R. Marker and Remains of
D.N.R. Bearing Tree described in "B"
New Witnesses:
Spruce 14" N31°E(M.B.) 29.68' Nail/Tag
Spruce 8" N77°E(M.B.) 26.72' Nail/Tag
Spruce 3" S31°E(M.B.) 10.68' Nail/Tag
Carsonite Marker Placed 1.0' South

C-12 Set 2 $\frac{1}{2}$ " Stamped D.C. Remon. Corner at
Mid-Point on Line between Section Corners
 $\frac{1}{2}$ Mile North and $\frac{1}{2}$ Mile South.
New Witnesses:
Oak 16" S50°E(M.B.) 66.71 Nail/Tag
Oak 16" N6°W(M.B.) 53.00' Nail/Tag
Maple 6" N60°E(M.B.) 90.14' Nail/Tag
R.Pine 14" S56°W(M.B.) 130.71 Nail/Tag
Carsonite Marker 1.0' South

Signed by Robert F. Perkins
Surveyor's Michigan License No. 12027

Date Nov. 6, 1998



0027383