also T44N-R29W K13 also T43N-R28W A03

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

also T43N-R28W A03

Dickinson	_ Located in:	Corner Code #						
(County) Felch Township 1. Public Land Survey	T 43N R 29W T 43N R 29W T R	K01 M03						
2. Property Controlling in Section	S T R S T R		i					
3. Miscellaneous Property in Sec.	S T R S T R		Regis	ster of Dee	ds Stamı	p & File	e Numt	er
4. Lot No. Res. Private Claims	corded Plat		1 A B	C D E	F G	H T	J K	L M
	7/12/20 in a field survey on 7/12/20	do hereby state	3 - 7-	8-	9	10	_11	12
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of 6					13			
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established re-established, monumented, recovered, found as expressed below:			9	20		22	_23_	-24-
NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.			10 30-	29	33	27-	-26- -35-	25-
man manage despit and commons			13		Ī			

A. Description of original monument and accessories and/or subsequent restoration:

(KO1) Corner common to Sections 1, 2, 35 and 36. 1846: Wm., John, & Austin Burt, DS. Set Cedar post witnessed by: Cedar 12 NO5E 25 links (16.50'); Cedar 2 N44W 13 links (8.58'); 1958: Michigan DNR (Billy Buckler PS#8887) Set 1" pipe with 4" brass cap witnessed by 10" White Birch SO2W 19 links (12.54'), 9" White Birch N28E 34 links (22.44').

(MO3) Corner common to Sections 1, 6, 7 and 12. 1846: Wm., John, & Austin Burt, DS. Set Spruce post witnessed by: Spruce 4 S40E 11 links (7.26'); Spruce 4 N87W 24 links (15.84'); 1969: Michigan DNR (Arthur Enger PS#13581) Set 1" x 36" iron pipe with 4" aluminum cap witnessed by Black Spruce 5 N17 1/2E 22 1/2 links (14.85'), Black Spruce 5 S56W 10 links (6.60'), Black Spruce 5 S40E 14 links (9.24').

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(KO1) Accepted found MDNR Monument and existing NBT Witness remains (all down & dead). Left MDNR monument in place and rewitnessed. Accepted found MDNR Monument and Witness remains as a careful and faithful REESTABLISHMENT of the position of the original corner.

(MO3) Accepted found MDNR Monument and Three existing Witnesses (all down & dead). Left MDNR monument in place and rewitnessed. Accepted found MDNR Monument and Witness remains as a careful and faithful REESTABLISHMENT of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(KO1) DNR monument	(MO3) DNR monument						
9" W. Birch N34E 8.39' (S36,NBT)	6" B. Spruce N43E 11.96' (S6,NBT)						
4" Maple S41E 30.90' (S1,NBT)	8" B. Spruce S63E 37.11' (S7,NBT)						
14" W. Birch S37W 43.15' (S2,NBT)	6" B. Spruce S44W 10.04' (S12,NBT)						
8" W. Birch N70W 17.14' (\$35,NBT)	7" B. Spruce N39W 14.01' (S1,NBT)						
All trees are blazed, scribed, painted,	All trees are blazed, scribed, painted,						
and signed. Measurements are to nail in	and Measurements are to nail in						
side of tree, bearings are magnetic, A	and the commander of the second secon						
carsonite rail was set North 1.5 feet.	carsonite rais was set North 1.5 feet.						
Signed by	JEREMY J. Date. July 19, 2012						

Surveyor's Michigan License No. 50447

For the Michigan Department of Natural Resources

PROFESSIONAL Offisury Sylory Fa o : N STATE ROARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971

20092

200