

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T. 43. NR. 29W. . .

----- Dickinson ----- COUNTY

DESCRIPTION OF CORNER Section corner common to Section 4, 5, 8 and 9. -----

DESCRIPTION OF CORNER MONUMENT 1" pipe with 4" brass cap. -----

WITNESSES TO CORNER Cedar 6" S78W 11 links -----

Marked S 8 NBT -----

Black Spruce 10" N46E 5 $\frac{1}{2}$  links -----

Marked S 4 NBT -----

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR  
RESTORED.

This corner replaced from 1 original cedar bearing tree (cedar 9 N63E5) in excellent  
condition. Old post nearby. Corner was found while cruising timber in this area.  
Corner placed and witnessed on December 19, 1960.

SURVEYORS SEAL

  
SIGNED Henry S. Peterson  
REGISTERED LAND SURVEYOR DATE 12-9-60