

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

DICKINSON COUNTY

FOR CORNERS OF --:	LOCATED IN --:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY _____	T. 43 N. 3 R. 29 W ^{NE}	D7
2. PROPERTY CONTROL- ING IN SECTION 20 _____	T. 43 N. 3 R. 29 W ^{NE}	14, 2, 1
3. MISCELLANEOUS PROPERTY IN SECTION _____	T. _____ N. _____ E. S. _____ R. _____ W.	
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND
FILING NUMBER

I, Keith L. Sackett, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on See Below, 19____, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

Corner 14: Not set on original survey nor subsequently apparently.
 Corner D7: Original monument and accessories not found. Old fence corner N55W 38.5 ft.
 Corner 2: Not set on original survey nor subsequently apparently. Old fence corner S86W 26.4 ft.
 Corner 1: Not set on original survey nor subsequently apparently.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

Corner 14: Established 5-21-81 midway on line between section corner south and $\frac{1}{4}$ corner north.
 Corner D7: Restored 5-18-81 midway on line between section corners north and south.
 Corner 2: Established 5-18-81 midway on line between section corner east and $\frac{1}{4}$ corner west.
 Corner 1: Established 5-18-81 midway on line between $\frac{1}{4}$ corner east and section corner west.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Corner 14: Set 1" I.D.x32" Iron Pipe with 4" alum. cap. 8" Elm S62E 31.2 ft. 1/16S,BT 6" Basswood N80W 38.9 ft. 1/16S,BT	Corner 1: Set 1" I.D.x36" iron pipe with 4" alum. cap. 8" Sugar S42E 22.3 ft. 1/16S,BT 8" Sugar S87W 25.1 ft. 1/16S,BT 5" Sugar N36E 14.8 ft. 1/16S,BT
Corner D7: Set 1" I.D.x32" iron pipe with 4" alum. cap. 6" Sugar N64E 17.1 ft. $\frac{1}{4}$ S,NBT 7" Sugar S40W 11.8 ft. $\frac{1}{4}$ S,NBT 5" Sugar S57E 30.1 ft. $\frac{1}{4}$ S,NBT	
Corner 2: Set 1" I.D.x32" iron pipe with 4" alum. cap. 7" Sugar S20E 8.6 ft. 1/16S,BT 4" Sugar N26W 11.6 ft. 1/16S,BT 5" Sugar S50W 24.8 ft. 1/16S,BT	

SIGNED BY _____ DATE _____

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____

APPROVED AND SIGNED BY Keith L. Sackett DATE 10-22-81

CHIEF OF SURVEY PARTY
MICHIGAN REGISTERED LAND SURVEYOR
Keith L. Sackett
Department of Natural Resources

SURVEYOR'S MICHIGAN REGISTRATION NO. 19006

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
REVISED MAY 14, 1975

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET