REMONUMENTATION

APR 27 1995

~~1	 1100	TO BE

ACMANDEDICA	LAND CORNE	IN NECONDATION CENTIFICA	
COMMISSION	Filing Require	ement of Act 74, Mich. P.A. 19	70 8-2 2 1
For corners in	_ ,		70.00
Dickinson	Located In:	Corner Code ##	5 5 7
(County)	Located iii.	Conner Code	
		() 1 mm	-8 & ORDE
1. Public Land Survey	Т <u>ЦЗМ</u> Я <u>ЗОЖ</u>	E-5 8 (F-5)	to the second se
2	T R		
	T R		
	TR		
			9 22
Property Controlling	S T R		
in Section	S T R		
Miscellaneous			Register of Deeds Stamp & File Number
Property in Sec.	S T R		
	-		
4 1 ot No	ecorded Flat	<u> </u>	— ABCDEFGHIJKLM
G. Fillate Chamio		'	2 5 4 4 3 2 1 1
		!	3
•			
Editord Verienks	Senter	ber 2 1994	
Formato Variatika	in a field survey on Septem		5
do hereby certify that under requ	direments of P.A. 74, Michigan P.A.	of 1970, the corner points mentioned d rules therefore as required in the	6 18 17 16 15 14 13
in lines 1 and 2 above were in	ctions of the United States Depart	tment of the Interior, Bureau of Land	7
Management or by a decree of a	Court of Law and/or that the corne	r points mentioned in lines 3, 4 and 5	8 10 20 21 22 23 24
chave were in conformance with	o the rules of the Michigan Board (of Land Surveyors or by a Decree of a	
Court of Law established re	e-established monumented re-r	nonumented, recovered, found as	9
expressed below:	, 20(42), 21(12)		10 30 29 28 27 26 25
*	orners, all in the same town ar	nd range may be recorded	11
	milers, all in the same town as	id lange, may be recorded	12 31 32 33 34 35 36
on this certificate.		:	
			13
	nonument and accessories and	d/or subsequent restoration:	** 00 31
E-5 Wood Post	Y. Birch 18 S32E 26	lks. Y. Birch 12 N64	W 32 lks.
l inch Iron	Pipe set by persons	unknown.	
F-5 Wood Post	Codon 6 Nobil 25 1ks	. Y. Birch 12 S20E 3	is iks.
r-5 wood rost	Cedar C NZHW Z) INC	se it with the profit of	
		;	
			·
		:	
R Description of corner ev	vidence found and/or method a	applied in restoring or reestablish	ing corner:
E-5 Found a 1 i	nch iron pipe with a	old broken-down lence i	running is mile north and
a quarter mile t	to the east. Pipe is	also on the extended ce	enterline of the old county
road from the we	st. Accepted iron pi	pe as the Section corne	er and replaced it with a
	Survey cap and rod.	•	
Dioningon of miles	3.1.		
E E No ovidonos	of original corner (or accessories found. S	let Quarter corner by
e ditanta on C-4	or original conice of	point and on line between	on the cention corners
		OTHE SHOT OH TIME DE DINGE	il Mie Becoton Collista
⅓ mile to the ea	ist and west.		ACCEPTED BY THE DICKINSON COUNTY
			SURVEY PEER GROUP AS THE OFFICIAL
			CORNER UNDER MICHIGAN PUBLIC ACT
		4	345 OF 1990 AT A MEETING HELD ON
			<u> </u>
			C. S. F.
		1	COUNTY REPRESENTATIVE
C. Description of monumer	nt for corner and accessories	established to perpetuate locating	the position of the corner:
		cap on a three foot Alu	
5-7- 33 MAR	TE 23 CA fact Manage	A NIOU 53 17 feet.	Maple 11 S30W 42.85 feet.
Oak II NI	name a corp f co	2004 JAN JJ. I 1880.	Troping mm Phots Merch Tools
Dbl. White	Birch 3 S35E 6.01 f	.66.0.€	
		_	
F-5 2½ inch Dic	kinson County Survey	cap on a three foot Alu	minum rod.
Dbl. Maple	8 S57E L8.82 feet.	Maple 10 577 W 43.5	7 feet.
		ole 9 N23E 35.17 feet.	
Veda 17 N	more polycomore with		
			FOR MICE
			The second of the
			To SERWARD & SA
	•		LATIANKA B
0 -	011	a	Show 6 1995 KAZIANKA
Signed by Elevand	1 Kayranka	Date Septem	hber 6, 1994 : LAND
- 9	11.765		EDWARD KAZIANKA LAND SURVEYOR
Surveyor's Michigan License	∍ No. <u>±410</u> 2	FORM /	APPROVED BY MICHIGAN WATE BOARD OF LAND BUTTEYORS, JAN 28 177
			A C 4 1 A 7 GEVES ED WAY TAKED TO THE

Liber 2 Page 101