

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Dickinson	Located In:	Corner Code #
(County)		
WEST BRANCH TOWNSHIP		
1. Public Land Survey	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S 21 T 44N R 27W	03
	S 21 T 44N R 27W	04
	S _____ T _____ R _____	_____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
4. Lot No. _____, Recorded Plat _____		
5. Private Claims _____		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

9/23/2013AD  
9/23/2013AD  
Jeremy J. Pipp, in a field survey on do hereby state  
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2  
above were in conformance with regulations and rules therefore as required in the current manual of survey  
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of  
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with  
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,  
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded  
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(03) North One-Sixteenth corner common to Sections 20 and 21. Not set in original  
survey, no evidence of subsequent establishment.

(04) Northwest One-Sixteenth corner of Section 21. Not set in original survey, no  
evidence of subsequent establishment.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(03) Corner position established mid-point and on-line between the West One-Quarter  
corner and the Northwest corner of Section 21.

(04) Corner position established at the intersection of the North and West One-  
Sixteenth lines of Section 21.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(03) DNR monument  
8" Maple N45E 30.51' (1/16S,BT)  
9" Maple S28E 21.17' (1/16S,BT)  
5" Spruce S51W 22.62' (1/16S,BT)  
11" Maple N35W 35.84' (1/16S,BT)

All trees are blazed, scribed, and  
painted. Measurements are to nail in  
side of tree, bearings are magnetic.

Signed by  
Surveyor's Michigan License No. 50447

(04) DNR monument  
12" B. Spruce N43E 9.39' (1/16S,BT)  
6" B. Spruce S44E 27.88' (1/16S,BT)  
6" B. Spruce S38W 7.05' (1/16S,BT)  
7" Maple N51W 21.54' (1/16S,BT)

All trees are blazed, scribed, and  
painted. Measurements are to nail in  
side of tree, bearings are magnetic.

JEREMY J. PIPP  
PROFESSIONAL SURVEYOR  
Date October 1, 2013

For the Michigan Department of Natural Resources, Forest Resource Division