

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Dickinson	Located In:	Corner Code #
(County)		
WEST BRANCH TOWNSHIP		
1. Public Land Survey	T 44N R 27W	D08
	T R	
	T R	
2. Property Controlling in Section	S T R	
	S 21 T 44N R 27W	08
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. , Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

I, Jeremy J. Pipp, in a field survey on 9/23/2013AD do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(D08) Center One-Quarter Corner of Section 20. Not set in original survey. Found Post
and Water pipes North +/-19 feet from calculated position.

(08) Center-West One-Sixteenth corner of Section 21. Not set in original survey, no
evidence of subsequent establishment.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(D08) Corner position established at the intersection of the North-South and East-West
One-Quarter lines of Section 20.

(08) Corner position established mid-point and on-line between the Center One-Quarter
corner and the West One-Quarter corner of Section 21.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(D08) DNR monument
5" Poplar N38E 13.40' (1/4S,BT)
8" Spruce S28E 39.93' (1/4S,BT)
12" Spruce S85W 53.80' (1/4S,BT)
7" W. Pine N73W 69.71' (1/4S,BT)

All trees are blazed, scribed, and
painted. Measurements are to nail in
side of tree, bearings are magnetic.

(08) DNR monument
6" ASH N14E 14.84' (1/16S,BT)
7" Maple S87E 7.02' (1/16S,BT)
7" Maple S22E 19.90' (1/16S,BT)
4" Ironwood N70W 10.20' (1/16S,BT)

All trees are blazed, scribed, and
painted. Measurements are to nail in
side of tree, bearings are magnetic.

Signed by Jeremy J. Pipp
Surveyor's Michigan License No. 50447

For the Michigan Department of Natural Resources, Forest Resource Division



Date October 1, 2013

20293

20292