Ilso T44N-R28W M05 ilso T44N-R28W M06

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Dickinson	Located In:	Corner Code #	
(County) WEST BRANCH TOWNSHIP I. Public Land Survey	T 44N R 27W	A05	
1. Fublic Land Survey	T 44N R 27W	A06	
2. Property Controlling n Section	S T R S T R S T R		
3. Miscellaneous Property in Sec.	STR STR		Register of Deeds Stamp & File Number
4. Lot No. , Rec 5. Private Claims	orded Plat		ABCDEFGHIJK
	9/16/2013	BAD	2 6 5 4 3 2

Jeremy J. Pipp , in a field survey on 9/16/2013AD hat under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey 50 nstructions of the United States Department of the Interior, Bureau of Land Management or by a decree of 6 I Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with 7 he rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, g e-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

10 11 12

A. Description of original monument and accessories and/or subsequent restoration: 1846: Austin Burt, DS. Set (AO5) Section corner common to Sections 7, 12, 13, and 18. Hemlock Section corner post witnessed by Maple 12 S17W 19 links (12.54'), Fir 6 N23E 19 links (12.54'), Y. Birch 12 S84E 34 links (22.44'), Y. Birch 20 N40W 27 links (17.82'). 1987: Michigan DNR (David Babbitt PS#21558) Set 1" pipe with 4" Aluminum cap witnessed by 15" W. Pine N56E 34.9', 10" W. Pine S39E 23.1', 9" W. Pine S72W 5.1', 5" R. Maple N47W 18.5'.

(A06) Quarter corner common to Sections 13 and 18. 1846: Austin Burt, DS. Set Cedar quarter section corner post witnessed by Y. Birch 16 S32W 06 links (3.96'), Y. Birch 8 N63E 20 links (13.20'). 1987: Michigan DNR (David Babbitt PS#21558) Set 1" pipe with 4" Aluminum cap witnessed by 12" W. Pine N40E 18.1', 10" W. Pine N65E 33.55', 12" H. Maple \$30W 27.1', 14" W. Pine N74W 36.8'.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(AO5) Accepted found MDNR Monument and four existing NBT Witnesses. Position is accepted as a careful and faithful REESTABLISHMENT of the position of the original corner.

(A06) Accepted found MDNR Monument and four existing NBT Witnesses (NW W. Pine is a dead stub). Position is accepted as a careful and faithful REESTABLISHMENT of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

EX 22" W. P	ine N60E	35.12'	(S 7,NBT)		
EX 14" W. P	ine S35E	23.53	(\$ 18,NBT)		
EX 13" W. P	ine S81W	5.31'	(S 13,NBT)		
EX 12" Mapl	.e N43W	18.53'	(S 12,NBT)		
All trees a	re blazed,	scribed	, painted,		
and signed. Measurements are to nail in					
side of tree, bearings are magnetic. A 🦯					
Carsonite r	ail was se	t North	1.5 feet.// ~		
Signed by			100 a Ca		

For the Michigan Department of Natural Resource

DNR monument

(A06) DNR monument EX 18" W. Pine N49E 18.75' (1/4S,NBT) EX 12" W. Pine N75E 33.89' (1/4S,NBT) EX 19" Maple S29W 27.33' (1/4S,NBT) \$59W 51.20' (1/4S,NBT) 18" W. Pine All trees are blazed, scribed, painted, and signate Aleasurements are to nail in sid of True Coparings are magnetic. A Casanite rail was set North 1.5 feet.

JEREMY Date

FESSION

October 1, 2013

Revised Jan., 1983

Rervised Oct., 1995

PIPP PROFESSIONAL

est RSMAYEDINGOn

N STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 Revised May 14, 1975

20279

20280

(A05)