

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Dickinson (County) Located In: Corner Code #
WEST BRANCH TOWNSHIP
1. Public Land Survey T 44N R 27W C07
T 44N R 27W C08
2. Property Controlling in Section S T R
S T R
S T R
3. Miscellaneous Property in Sec. S T R
S T R
4. Lot No. , Recorded Plat
5. Private Claims

Register of Deeds Stamp & File Number

Table with 13 rows and 13 columns (A-M). Contains numbers 1-36 and two dots at (C,7) and (C,8).

9/24/2013AD
9/24/2013AD
Jeremy J. Pipp, in a field survey on 9/24/2013AD do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(C07) Section corner common to Sections 17, 18, 19, and 20. 1850: John Burt, DS. Set
Cedar section corner post witnessed by Cedar 18 S59E 35 links (23.10'), Cedar 10 N49W
26 links (17.16'). 1984: Michigan DNR (David Babbitt PS#21558) Set 1" pipe with 4"
Aluminum cap witnessed by 10" Spruce N34E 4.45', 14" Spruce N40E 20.05', 8" Spruce N63E
48.00', 7" Spruce S56E 39.60'.

(C08) Quarter corner common to Sections 19 and 20. 1850: John Burt, DS. Set Sugar
quarter section corner post witnessed by Y. Birch 18 N36W 30 links (19.80'), Sugar 18
S17E 17 links (11.22'). 1984: Michigan DNR (David Babbitt PS#21558) Set 1" pipe with 4"
Aluminum cap witnessed by 4" Aspen N68E 31.65', 4" Aspen S60E 21.50', 10" Aspen S32W
8.45', 9" Aspen N55W 14.05'.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(C07) Accepted found MDNR Monument and four existing NBT Witnesses. Position is
accepted as a careful and faithful REESTABLISHMENT of the position of the original
corner.

(C08) Accepted found MDNR Monument and NBT Witnesses (all dead & down). Position is
accepted as a careful and faithful REESTABLISHMENT of the position of the original
corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(C07) DNR monument
EX 15" Spruce N41E 4.50' (S 17,NBT)
EX 18" Spruce N44E 20.81' (S 17,NBT)
EX 18" Spruce N67E 47.60' (S 17,NBT)
EX 18" Spruce S47E 39.81' (S 20,NBT)
All trees are blazed, scribed, painted,
and signed. Measurements are to nail in
side of tree, bearings are magnetic. A
Carsonite rail was set North 1.5 feet.

(C08) DNR monument
6" Poplar N19E 19.41' (1/4S,NBT)
4" Poplar S65E 13.90' (1/4S,NBT)
5" Poplar S50W 22.69' (1/4S,NBT)
4" Poplar N50W 23.20' (1/4S,NBT)
All trees are blazed, scribed, painted,
and signed. Measurements are to nail in
side of tree. Bearings are magnetic. A
Carsonite rail was set North 1.5 feet.

Signed by [Signature]
Surveyor's Michigan License No. 50447

Date October 1, 2013

For the Michigan Department of Natural Resources, Forest Resource Division

