

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF:-	LOCATED IN:-	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY_____	T. <u>44</u> ^{N.} S. R. <u>29</u> ^{W.} E.	<u>F3 & G3</u>
2. PROPERTY CONTROLL- ING IN SECTION_____	T. _____ N. _____ E. _____ S. _____ R. _____ W. _____	_____
3. MISCELLANEOUS PROPERTY IN SECTION_____	T. _____ N. _____ E. _____ S. _____ R. _____ W. _____	_____
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND
FILING NUMBER

I, Arthur O. Enger, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on see below, 19____, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

Corner F3 (1/4 corner between Sections 4 & 9, T44N, R29W):

Cedar Post (Not found. No subsequent monuments found.)
Y. Birch 10 N 5W 15 (Not found. No subsequent accessories found.)
Y. Birch 8 S25W 33 (" " " " " ")

Corner G3 (Section Corner 3, 4, 9, & 10, T44N, R29W):

Cedar Post (Not found. No subsequent monuments found.)
Tamarack 16 S72E 13 (Not found. No subsequent accessories found.)
Cedar 5 N50W 29 (" " " " " ")

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

Corner F3: Re-established proportionately on line between Sec. Corners 39.889 ch. W and 39.879 ch. E.

Corner G3: Re-established by double proportionate measurement between original sec. corners 79.768 ch. W and 79.568 ch. E and an original 1/4 cor. 40.029 ch. N and a stream crossing 30.840 ch. S. (Note: The record distance between Sec. Cor. and stream is 30.50 ch. It is believed that a blunder occurred someplace in this segment of line during the original survey measurement.)

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Corner F3: 1" I.D. x 36" iron pipe with 3 3/4" aluminum cap.
Cedar 6 N70°W (mag.) 21.8 ft. "1/4S, NBT"
Cedar 10 N77°E (mag.) 22.7 ft. "1/4S, NBT"
Corner G3: 1" I.D. x 36" iron pipe with 3 3/4" aluminum cap.
Cedar 8 N58°W (mag.) 53.0 ft. "S4, NBT"
Cedar 10 S42°W (mag.) 39.9 ft. "S9, NBT"

SIGNED BY _____ DATE _____

SURVEYOR'S MICHIGAN REGISTRATION NO. _____ (SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY Carl R. Johnson DATE January 20, 1976
CARL R. JOHNSON CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY Arthur O. Enger DATE January 20, 1976
ARTHUR O. ENGER MICHIGAN REGISTERED LAND SURVEYOR

Michigan Department of Natural Resources
SURVEYOR'S MICHIGAN REGISTRATION NO. 13581

