

**LAND CORNER RECORDATION CERTIFICATE**  
**FILING REQUIREMENT OF ACT 74, MICH. P.A.1970**

FOR CORNERS OF:-	LOCATED IN:-	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY_____	T. <u>44</u> <sup>N.</sup> <del>XX</del> , R. <u>29</u> <sup>XX</sup> <del>W.</del>	<u>C4</u>
2. PROPERTY CONTROLL- ING IN SECTION <u>8</u>	T. <u>44</u> <sup>N.</sup> <del>XX</del> , R. <u>29</u> <sup>XX</sup> <del>W.</del>	<u>10</u>
3. MISCELLANEOUS PROPERTY IN SECTION_____	T. _____ <sup>N.</sup> <del>S.</del> , R. _____ <sup>E.</sup> <del>W.</del>	_____
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND  
FILING NUMBER

I, Arthur O. Enger, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on August 18, 19 75, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on \_\_\_\_\_, 19\_\_\_\_, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

**A. Description of original monument and accessories and/or subsequent restoration:**

Corner C4 (1/4 corner between Sections 7 & 8, T44N, R29W):

Tamarack Post	(Not found. No subsequent monuments found.)
Spruce 8 S30E 45	( " " " " accessories " )
Tamarack 12 N40W 35	( " " " " " " )

Corner 10 (South 1/16 corner between Sections 7 & 8, T44N, R29W):

Not established in original survey and by approximation only, subsequently.

**B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:**

Corner C4: Re-established on line between probable original sec. corners 39.953 ch. to N and to S. Found ledge of rock 15 ft. high course ESE 2 ch. S of corner, as mentioned in original field notes.

Corner 10: Established on line between Sec. Cor. 19.976 ch. S and 1/4 cor. 19.976 ch. N. Found an 8" black spruce blazed on 4 sides S61°W 9.1 ft. for an approximate corner.

**C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:**

Corner C4: 1" I.D. x 36" iron pipe with 3 1/2" aluminum cap and 1/2" x 12" iron rod welded to below-ground end, set in mound of rocks.

Tamarack 12 N49 1/2° E (mag.) 43.1 ft. "1/4S, NBT"  
Tamarack 6 S63° E (mag.) 37.5 ft. "1/4S, NBT"

Corner 10: Same kind of monument as for Corner C4.

B. Spruce 6 S16°W (mag.) 6.5 ft. "1/16S, BT"  
B. Spruce 8 N57°E (mag.) 12.2 ft. "1/16S, BT"

Also squared and scribed an 8" black spruce N31°E (mag.) 1.1 ft. (to center of tree).

SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_

SURVEYOR'S MICHIGAN REGISTRATION NO. \_\_\_\_\_

(SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_

APPROVED AND SIGNED BY \_\_\_\_\_ DATE January 26, 1976

CHIEF OF SURVEY PARTY

MICHIGAN REGISTERED LAND SURVEYOR

Arthur O. Enger

Michigan Department of Natural Resources

SURVEYOR'S MICHIGAN REGISTRATION NO. 13581

