

**LAND CORNER RECORDATION CERTIFICATE**  
**FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970**

FOR CORNERS OF--	LOCATED IN--	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY_____	T. <u>44</u> N. <u>X</u> , R. <u>29</u> E. <u>X</u>	<u>A6</u>
2. PROPERTY CONTROLLING IN SECTION <u>18</u>	T. <u>44</u> N. <u>X</u> , R. <u>29</u> E. <u>X</u>	<u>15</u>
3. MISCELLANEOUS PROPERTY IN SECTION _____	T. _____ N. _____, R. _____ E. _____	_____
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND  
FILING NUMBER

I, Arthur O. Enger, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on see below, 19\_\_\_\_, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on \_\_\_\_\_, 19\_\_\_\_, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

**A. Description of original monument and accessories and/or subsequent restoration:**

Corner A6 (1/4 corner between Sections 13 & 18, T44N, R29-30W):

Cedar post	(Not found. No subsequent monuments found.)	
Sugar 8 S74W 56	( " " " " accessories " )	
Ironwood 7 N59E 12	( " " " " " " )	

Corner 15 (West 1/16 corner between Sections 18 & 19, T44N, R29W):

Not established in original survey nor subsequently, apparently.

**B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:**

Corner A6: Re-established 11/20/72 on line between Sec. Cor. 39.927 ch. to N and to S.

Corner 15: Established 9/25/75 proportionately on line between 1/4 cor. 20.144 ch. E and Sec. Cor. 20.093 ch. W.

**C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:**

Corner A6: 1" I.D. x 36" iron pipe with 4" aluminum cap.

W. Pine 15 N47°E (mag.) 54.9 ft.  
W. Pine 14 S64½°E (mag.) 32.7 ft.  
J. Pine 7 S28°W (mag.) 24.3 ft.

Note: Distances are to a nail with 3/4" brass washer stamped "REF MARKER" in notch on root collars of above trees.

Corner 15: 1" I.D. x 36" iron pipe with 3 3/4" aluminum cap.

Cedar 12 N22°W (mag.) 20.4 ft. "1/16S, BT"  
Cedar 14 N60°E (mag.) 40.0 ft. "1/16S, BT"

SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_

SURVEYOR'S MICHIGAN REGISTRATION NO. \_\_\_\_\_ (SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_

APPROVED AND SIGNED BY Arthur O. Enger DATE January 26, 1976

CHIEF OF SURVEY PARTY  
MICHIGAN REGISTERED LAND SURVEYOR

Arthur O. Enger

Michigan Department of Natural Resources

SURVEYOR'S MICHIGAN REGISTRATION NO. 13581

