

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

also T45N-R29W E13
for corners in

Dickinson	Located In:	Corner Code #
(County)		
ELCH TOWNSHIP		
1. Public Land Survey	T 44N R 29W	E01
	T 44N R 29W	E03
	T R	
2. Property Controlling	S T R	
n Section	S T R	
	S T R	
3. Miscellaneous	S T R	
Property in Sec.	S T R	
4. Lot No.	Recorded Plat	
5. Private Claims		

12/03/2012AD
12/03/2012AD
do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(E01) Corner common to Sections 32, 33, 4, and 5. 1846: John Burt, DS. Set Spruce post witnessed by: Y. Pine 14 N60E 277 links (182.82'); Y. Pine 14 N85W 192 links (126.72'); 1955: Michigan DNR (Billy Buckler PS#8887) Set 1" pipe with 4" Brass cap from original evidence witnessed by White Pine 18 S62W 192 links (126.72'); 1983: (unrecorded, UPEA files) William Donnon, PS#17618 LCRC lists witnesses 28" W. Pine S65W 127.41, 5" Tamarack S36W 36.89, 5" Tamarack N25W 58.68, & 4" Tamarack S81E 34.29'.

(E03) Corner common to Sections 4, 5, 8, and 9. 1848: John Burt, DS. Set Cedar post witnessed by: W. Pine 30 S69W 61 links (40.26'); W. Pine 30 N15E 19 links (12.54'); 1976: Michigan DNR (Arthur Enger PS#13581) Set 1" pipe with 3 3/4" aluminum cap from original evidence witnessed by White Pine 18 S84W 25.1', Tamarack 9 N38E 32.4'.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(E01) Accepted found MDNR Monument and Four existing (Two living & Two dead) NBT Witnesses. Left MDNR monument in place and rewitnessed. Accepted found MDNR Monument and Witness remains as a careful and faithful PERPETUATION of the position of the original corner.

(E03) Accepted found MDNR Monument, remains of OBT's, and two existing NBT Witnesses. Left MDNR monument in place and rewitnessed. Accepted found MDNR Monument and Witness remains as a careful and faithful PERPETUATION of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(E01) DNR monument
EX 4" B. Spruce S80E 34.35' (- , -)
EX 5" B. Spruce S39W 36.89' (- , -)
4" B. Spruce S79W 44.93' (S5,NBT)
4" B. Spruce N16W 45.13' (S32,NBT)

All trees are blazed, scribed, painted, and signed. Measurements are to nail in side of tree, bearings are magnetic. A carsonite rail was set North 1.5 feet.

Signed by Jeremy J. Pipp
Surveyor's Michigan License No. 50447

(E03) DNR monument
19" Spruce N04W 14.21' (S5,NBT)
EX 11" Tamarack N44E 32.89' (- , -)
6" Spruce S12W 15.45' (S8,NBT)
EX 22" W. Pine S87W 25.75' (- , -)

All trees are blazed, scribed, painted, and signed. Measurements are to nail in side of tree, bearings are magnetic. A carsonite rail was set North 1.5 feet.

Signed by JEREMY PIPP Date July 18, 2013
PROFESSIONAL
APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
FORM 50447

For the Michigan Department of Natural Resources, Forest Reserve Division

20143

20142

Revised May 14, 1975
Revised Jan., 1983
Revised Oct., 1995