

also T45N-R29W G13  
also T45N-R29W F13  
For corners in

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

Dickinson	Located In:	Corner Code #
(County)		
FELCH TOWNSHIP		
1. Public Land Survey	T 44N R 29W	G01
	T 44N R 29W	F01
	T R	
2. Property Controlling in Section	S T R	
	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. , Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

12/03/2012AD  
12/03/2012AD  
do hereby state  
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(G01) Corner common to Sections 33, 34, 3, and 4. 1846: John Burt, DS. Set Spruce post witnessed by: Spruce 10 N16E 17 links (11.22'); Spruce 10 N79W 14 links (9.24'); 1956: Michigan DNR (Billy Buckler PS#8887) Set 1" pipe with 4" Brass cap witnessed by 9" Cedar N60W 11 links (7.26'), 8" Cedar S21W 39 links (25.74'), & 9" Cedar S76E 29 links (19.14').

(F01) Quarter corner common to Sections 33 and 4. 1846: John Burt, DS. Set Cedar Post witnessed by W. Pine 30 N30E 5 links (3.30'), Cedar 14 N59W 7 links (4.62'). 1956 Michigan DNR (Billy Buckler PS#8887) set 1" I.D. with 4" Brass cap from original evidence witnessed by 12" W. Pine S81E 24 links (15.84') & 14" Red Pine N09W 59 links (38.94').

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(G01) Accepted found MDNR Monument and Three existing NBT Witnesses. Left MDNR monument in place and rewitnessed. Accepted found MDNR Monument and Witness remains as a careful and faithful REESTABLISHMENT of the position of the original corner.

(F01) Accepted found MDNR Monument and Two existing NBT Witnesses. Left MDNR monument in place and rewitnessed. Accepted found MDNR Monument and Witness remains as a careful and faithful PERPETUATION of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(G01) DNR monument  
8" B. Spruce N13E 20.60' (S34,NBT)  
EX 14" Cedar S72E 19.12' ( - , - )  
EX 13" Cedar S22W 25.31' ( - , - )  
EX 18" Cedar N55W 7.53' ( - , - )  
All trees are blazed, scribed, painted, and signed. Measurements are to nail in side of tree, bearings are magnetic. A carsonite rail was set North 1.5 feet.

(F01) DNR monument  
EX 32" W. Pine S76E 16.33' ( - , - )  
15" W. Pine S11E 38.82' (1/4S,NBT)  
26" W. Pine S76W 57.41' (1/4S,NBT)  
EX 23" R. Pine N04W 39.59' ( - , - )  
All trees are blazed, scribed, painted, and signed. Measurements are to nail in side of tree, bearings are magnetic. A carsonite rail was set North 1.5 feet.

Signed by  
Surveyor's Michigan License No. 50447

Date July 18, 2013

For the Michigan Department of Natural Resources, Forest Management Division

20144

20145

