

88,

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in Dickinson Located In: Corner Code #1  
(County)

1. Public Land Survey T 44R 29W #1  
T     R          
T     R          
T     R        

2. Property Controlling S     T     R      
In Section S     T     R    

3. Miscellaneous S     T     R      
Property in Sec. S     T     R    

Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

	A	B	C	D	E	F	G	H	I	J	K	L	M
2													
3													
4													
5													
6													
7													
8													
9													
10													
11													
12													
13													

I, Stephan J. Szyszkoski, in a field survey on JANUARY 19, 1994, 19\_\_\_\_, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(N1) Quarter corner common to Section 3 T44N-R29W, and Section 34 T45N-R29W. Corner restored in 1956 by Billy D. Buckler, RLS, as follows: Replaced 1/4 corner from one W. Pine stump (probably) B.T. Distance checks east and west along township line. Placed 1" pipe with 4" brass cap. NBTs: 7" Jack Pine S03E 18.5 links, 5" Jack Pine N24W 12 links.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(N1) Recovered Buckler's monument, a 1" pipe with 4" dia. brass Mich. Department of Conservation cap, at record bearing and distance from the 1956 NBTs, both dead and down. Left the monument in place and marked 4 new witness trees as described below.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(N1) Found 1" pipe with 4" brass cap.  
Blazed and scribed the following new bearing trees:  
7" Jack Pine S20W 8.9' "1/4S NBT"  
5" Jack Pine N09W 10.1' "1/4S NBT"  
12" Jack Pine N09W 14.8' "1/4S NBT"  
8" Jack Pine S01E 12.4' "1/4S NBT"  
Bearings magnetic.



Signed by Stephan J. Szyszkoski Date 2-7-94  
Surveyor's Michigan License No. 33986