

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Dickinson	Located In:	Corner Code #
(County)		
1. Public Land Survey	T 44N R 30W	G8
	T R	
	T R	
2. Property Controlling in Section	S T R	
	S 8 T 44N R 30W	3
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. , Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5			4		3		2		1	
3													
4	7		8			9		10		11		12	
5													
6	18		17			16		15		14		13	
7													
8	19		20			21		22		23		24	
9													
10	30		29			28		27		26		25	
11													
12	31		32			33		34		35		36	
13													

I, Stephan J. Szyszkoski, in a field survey on 3 08/05/2010 do hereby state

that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(G8) Quarter corner common to Sections 21 and 22. The position for the corner falls in Edey Lake and is not monumented. 1991 - Corner position established by Edward Kazianka RLS midway and on line between Section corners. Mr. Kazianka placed a witness corner to G8 on the South shore of the lake 808.0' south of the corner position. 1" iron pipe with 4" alum. cap. Twin Maple 12 S06E 20.34', Maple 9 S72W 29.02', Maple 3 N52W 17.36'.

(3-Sec. 8) North 1/16 corner between Sections 7 and 8. Not established in the original survey.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(G8) Found and accepted the 1991 Kazianka Witness Corner monument and used it, according to his record, to control both the position of G8 and the subsequent subdivision of Section 21. Established a 2nd Witness corner 800.0' west of the position for G8 and on the E-W 1/4 line of Section 21. The Witness corner is 1845.39' east of the Center of Section 21.

(3-Sec. 8) Established the corner midway and on the Section line between Quarter corner 1333.30' south and Section corner 1333.30' north

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(G8) Set 1"IDx32" I.pipe with 4" alum. MDNR cap 800.0' West of the corner position and on the E-W 1/4 line of Section 21.
Set measuring nail with MDNR tag in the side of:
6" Maple N50E 24.8' mrkd "WC BT"
3" Maple S71E 20.2' do
9" Sugar N88W 12.1' do
10" Maple in clump N39W 15.8' do
Set sq'd cedar post adjacent.
Bearings are magnetic.

(3) Set 1"IDx32" I.pipe with 4" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
16" Cedar N19E 15.3' mrkd "1/16S BT"
5" Sugar S88E 20.4' do
4" Maple S16W 2.2' do
6" Sugar N20W 31.6' do
Set sq'd cedar post adjacent.
Bearings are magnetic.

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 12/09/2010

For the Michigan Department of Natural Resources and Environment, Forest Management Division

