

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Dickinson Located In: Corner Code #
Sagola Township
1. Public Land Survey T 44N R 30W MC W of K07
2. Property Controlling in Section S T R
3. Miscellaneous Property in Sec. S T R
4. Lot No. Recorded Plat
5. Private Claims

Register of Deeds Stamp & File Number

Table with 13 rows and 13 columns (A-M). Contains numbers 1-36 in a grid pattern.

I, Jeremy J. Pipp, in a field survey on 5/10/2012AD do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(MC W of K07) Meander Corner common to Sections 14 and 23 on the East side of Silver Lake. 1848: John Burt, DS. No post noted witnessed by: W. Pine 18 S28E 19 links (12.54'); Spruce 4 N9E 21 links (13.86'); 1973 Robert Perkins PS#12027 shows dimensions to a reestablished position of this MC, and notes Plat of Survey is 'referenced to a retracement of a survey of Government Lot 2 made in 1927 by J.E. Gingrass, C.E.'; 2003 Steven Applekamp PS#43045 sets 5/8" capped rebar per retracement of previous Perkins survey.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(MC W of K07) Accepted found PS#43045 Capped rebar. GLO distance from the Northeast corner to this position is 6.52 Chains (430.32 feet); this position falls in the sandy shore. Previously monumented witness position is 414.2 feet West of Northeast Corner and +/-75 feet from the Waters Edge. Position is accepted as a careful and faithful WITNESS TO the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(MC W of K07) DNR monument
4" W. Pine N56E 31.33' (MC,NBT)
5" W. Pine S68E 15.84' (MC,NBT)
6" W. Pine S13E 67.55' (MC,NBT)
4" Tamarack N24E 8.68' (MC,NBT)
All trees are blazed, scribed, painted, and signed. Measurements are to nail in side of tree, bearings are magnetic. A carsonite rail was set East 1.5 feet.



Signed by [Signature]
Surveyor's Michigan License No. 50447

Date July 18, 2012