

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:		Located In	Corner Code #
Emmet			
(County)			
1. Public Land Survey	T	36N R 4W	B-7
	T		
2. Property Controlling in Section	S 18	T 36N R 4W	12
	S	T	
3. Miscellaneous Property in Section	S	T	R
	S	T	R

4. Lot No: _____ Recorded Plat: _____

5. Private Claims: _____

I, Carl T. Kiiskila, in a field survey on October 30, 2008 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7	19		20		21		22		23		24		
8													
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

- B-7 GLO – 1840 – John Mullet – Set Qr. Section Post. 12 CS 1/16 Cor. Sec. 18, T36N, R4W
 Wit: Sugar 24 N57°W 13 links
 Sugar 15 S31°E 14 links
 2001 – Tom Swenor P.S.# 37282 – Set ½" bar on line
 between section corners on old North – South fence.
 Wit: 10" Maple S1°E 24.35'
 22" Twin Maple S86°W 13.46'
 12" Beech N25°W 18.67'
 14" Basswood N52°E 7.13'

B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

- B-7 Found ½" capped iron rod #37282 fitting T. Swenor's survey in section 18. Found no other evidence to dispute the location for the corner. 12 Set 5/8"x 34" rebar with P.S. cap#33981 per standard BLM procedure.
 Replaced found iron with stamped 4" aluminum DNR cap on 1"x36" galvanized pipe. Accepted found iron as the best available evidence of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- B-7 Stamped 4" Aluminum DNR cap on 1"x36" galvanized pipe. 12 5/8"x 34" rebar with P.S. cap#33981.
 Wit: N26°W 18.64' to set N&T on SW side 11" Beech
 N50°E 7.11' to set N&T on NW side 12" Basswood
 S84°W 13.44' to set N&T on N side 18" Maple
 S1°E 24.34' to set N&T on NE side 9" Maple
 N61°E 20.18' to set N&T on NW side 17" Maple
 Set Blue Carsonite Post 1' North
 Wit: N14°E 18.66' to set N&T on W side 16" S. Maple
 N50°W 30.08' to set N&T on SW side 8" S. Maple
 S30°W 43.57' to set N&T on NW side 12" S. Maple
 S30°E 4.61' to set N&T on NE side 11" Basswood
 Set Blue Carsonite Post with loc. tag 1' North

Signed by:

Carl T. Kiiskila

Date:

7-20-09

Surveyor's Michigan License No.:

33981

