.5			•
accordance with	PA 946, 1006	MONUMENTATION PROGRAM VER RECORDATION CERTIFICAT	E 1888 2601 PAGE 282
Co. Rep. A	Filing Requ	irement of Act 74, Mich. P.A. 197	
Date 11 - 15	- 15		mo S mm
For corners in			
Genesee	Located In:	Corner Code #	CORD CORD
(County)			
	<u>.</u>		· · · · · · · · · · · · · · · · · · ·
1. Public Land Sur	vey T 8N R 5E T R	J-5	
	Ť Ř		は、これには、これには、これには、これには、これには、これには、これには、これに
		SURVEYS	1018 6 \
 Property Control in Section 	Iling S T R	REMONUMENTATION	Register of Deeds Stamp & File Number
3. Miscellaneous	STR		
Property in Sec.	SR	APR 2 9 1996	
4 Lat No	, Recorded Plat	70 N M # 1030	
5. Private Claims		COMMISSION	- ABCDEFGHIJKL
			2 6 6 4
			3
I Jack N. Owen	s, Prof. Surveyor, in a field	survey on September 26,1995,	4 - 7 - 8 10 11 - 12
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the			5
current manual of survey instructions of the United States Department of the Interior, Bureau of Land			6 18 17 16 15 14 13
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a			7
Court of Law; esta expressed below;	blished, re-established, monumented,	re-monumented, recovered, found as	8 -19 20 - 21 22 - 23 24
expressed below,	•	•	9 20 00 07 07 06
	than 4 corners, all in the same to	wn and range, may be recorded	10 30 29 28 27 26 25
on this ce	ertificate.		12 31 32 33 34 35 36
A. Description of	original monument and accessories	and/or subsequent restoration:	13 32 33 34 30 30
1822 GLO - H.	Ball, DS set post and 2 access	ories	••
1 new acc 1920 - 1930 G 1970 REI - Fie 1971 REI - Fie 1974 Cert. Sur both done 1974 REI - Fie 1902 Cert. Sur L 2236, F	cessory. CRC witnesses, fnd stone; and ead notes sketch, fnd "T", no a sid sketch, no description of more. L 1889, pgs 520-521, by Dav. by Jan S. Fokens PS 21567; "Teld sketch, empty mon. box, no rv. L 2151, p 597, 1982 L 2153 to 580, 1986 unrecorded survey, and "T" & (1/2" iron 0.15" NE o	ccessories. onument, no accessories, measured id T. Rowe PS 11192; 1976 L 1964 " iron, measured between corners	hetween corners K-5 & J-5 p 294 & 1977, L 1989, p 417-418, K-5 & J-5, and 2 new accessories by Jan 8. Fokens PS 21567, 1985 67, all done by Jack N. Owens
(Continue	ed on back)		
B. Description of	corner evidence found and/or methy	od applied in restoring or reestablishing	corner:
•		(also 1/2" rod 0.15' NE of "T" ir	
1920-1930 Surveys (Pk in re	GCRC (18" hickory to NNW at 3	2.0', and P/P to SE at 72.2') and and 1 accessory from the 1986 up	l 1 accessory from 1982-1988 Cer.
between K-5 and 1.6' from the 18 and J-5 (differing 0.7' from the 18	J-5. Rowe Engineering in 1971 r 90 measurement). Rowe Engineer ng by only 0.9' from the 1890 r 90 measurement; and in 1988 mea	ring in 1974 measured 2614.00' (3: measurement); and in 1983 measured sured 2614.32' (differing by 0.60	een K-5 and J-5 (differing by only
(Continue	ed on back)		
C. Description of	monument for corner and accessor	ies established to perpetuate locating the	ne position of the corner: Peer Group, November 15, 1995.
kaanaanya.			
ACCESSORIES:			SE WICL
540°E 71.87' N15°H 32.92'	Fnd nail 4 washer in MNW fc l Fnd pk nail in SW root 30" h		The state of the s
\$55°₩ 36,97'	Fnd 1/2" rod & cap #20709 at	edge road	JACK N. *** OWENS
North 33,23'	Fnd 1/2" rod w/out cap leani: angle iron fnc post	,	LAND *
145°E 21.75'	Set 1/2" rod 6 cap ∦20709 in	rd. shoulder ± 0.5' below surface	SURVEYOR
"Genesee County I	rd Bernsten monument SS-A-5-BR- Remonumentation Corner 20709, I tube over stone with grout in s		No. 20709
	1 n		ARDS
Signed by	sh II. Vins	Date Dec ZK	, 1985
Surveyor's Michigan	n License No.' 20709	·	

•

MAY 31 2000

SECTION

4

- Description of original monument and accessories and/or subsequent restoration:
- REI Field sketch, find 1/2" iron in mon. box, measured between corners I-5
- 1985
- REI Field sketch, fnd 1/2" iron in mon. box, measured between corners I-5 and J-5, no accessories.

 REI Field sketch, fnd "T" in mon. box (also 6" piece of 5/8" smooth steel leaning over "T", used "T"), no accessories.

 Unrecorded survey, F-8081-86, by Jack N. Owens PS20709; 1989 L 2352 p 906, 1990 L 2402 p 393, both done by Faul N. Brown PS33134; 1990 L 2412 p 855, 1991 L 2426 p 8, 1993 L 2520 pgs 357-358, by Mark L. VanRaemdonck PS24622;

 "T" iron in mon box, measured between corners J-5 and J-6, and 1 new accessory REI Survey worksheet, no description of corners page accessories.
- 1988
- REI Survey worksheet, no description of corner, no accessories, measured between corners I-5 and J-5.5%;
- Unrecorded survey, #92-93-A, by Christopher W. Newman PS24607, found "T" iron in mon. box, no new accessories. 1992
- Description of corner evidence found and/or method applied in restoring or reestablishing corner:

I feel that the stone found under the "T" iron while visiting this corner during the 1995 Genesee County Remonumentation Program was probably set by a County Surveyor near the turn of the century. This stone had been found during the 1920's - 1930's GCRC and the turn of the century. This stone had been found during the 1920's - 1930's GCRC and was later raised with a "T" iron that dates back to 1970 when it was found by Rowe Engineering. We have no record demonstrating how the 1/2" rod 0.15' NE of the "T" iron was set, nor that it was used in any surveys, and we note that the older witnesses do not agree with its position. Upon review of the above mentioned evidence, I conclude that the "T" iron above a stone in a mon. box is a faithful and careful perpetuation of the position of the original corner.

TON, RSE J-5