

# LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:

Gladwin  
(County)

Located In

Corner Code #

1. Public Land Survey	T		R	
	T		R	
2. Property Controlling in Section	S 12	T 18N	R 1E	6
	S 12	T 18N	R 1E	7
3. Miscellaneous Property in Section	S	T	R	
	S	T	R	

4. Lot No: Recorded Plat:

5. Private Claims:

I, Craig W. McVean, in a field survey on Aug. 26, 2010 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

**NOTE:** Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Register of Deeds Stamp & File Number

1	A	B	C	D	E	F	G	H	I	J	K	L	M
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

6 - None

7 - 1930's - CCC Notes - N 1/8

1) Witness hole S50°W 50

2) Witness hole N50°E 50

- 1997 - DNR Survey Project No. - FM - 19-92 - C. Kiiskila - Drove 1" x 60' pipe with PS Cap beside found M. Schaaf Mon. (1 1/2" pipe in Conc.)

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

6 - NE 1/16 Corner Sec. 12, T18N, R1E - Set 2" Alum. Cap on 5/8" x 34" rebar per Standard BLM procedure.

7 - N 1/16 Corner common to Section 12, T18N, R1E & Sec. 7, T18N, R2E - Fd. 1" iron pipe with PS Cap #33981 per DNR Survey. 1" CIR accepted as the best available evidence of the position of the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

6 - Stamped 2" Alum. Cap on 5/8" x 34" long iron rebar  
N27°E 78.39' to set N & T in W. side 6" R. Maple  
S75°E 116.52' to set N & T in W. side 10" R. Maple  
S53°W 16.96' to set N & T in SE side Tri. 12" R. Maple  
N78°W 37.33' to set n & t IN n. SIDE 6" R. Maple

7 - 1" iron pipe with PS Cap #33981 - 1' above grade.  
NE 1' to Fd. Blue Carsonite Post with loc. tag  
S67°E 15.32' to set N & T in S. side 10" Oak  
S39°W 9.90' to Fd. N & T in SE side 8" Oak  
N54°W 13.34' to Fd. N & T in SW side 8" Oak  
N30°E 18.68' to Fd. N & T in W. side 5" R. Maple

Signed by:

*Craig W. McVean*

Date:

11/29/2012

Surveyor's Michigan License No.:

39088

