LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

Corner Code #

Located In

For Corners In: Gladwin

(County)																		
1. Public Land Survey		T	18N	R _	E	G1												
2. Property Controlling				_			2											
in Section	s	T		R R				ĺ										
Miscellaneous Property in Section	s	Т		R –														
Property in Section	s	T									Regis	ter of	Deed	is Sta	mp &	File N	lumbe	r
4. Lot No:	Recorde	d Pla	at:															
5. Private Claims:	Private Claims:												F	G Н	1 1	K	<u> </u>	
_						•		_	3	_ 6 -	<u> </u>		4-	3-	Ż			
I, <u>Craiq W. McVean</u> , in a field survey on <u>Aug. 3</u> , 2010 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1								4	 	_ի։	-	- 9 <mark>.</mark>	10-		,_	-12		
and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the									5	 			-		╅┥	+	+	
Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:									6 7		<u> </u>		-16	15-			-13	
									8	 19- 	2(╬—}-	-21 	 22- 		3 - -	_24	
NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.									9		士,		78-	1	+	_	35	
									11	ГÏ								
									12	31-	 3	12	-33	 - 34	35 1	5—	-36	
									13 ^l			ш.						
A. Description of original	monumer	nt an	d acces	sories	and/o	or subseq	uent rest	oration:	:									
of post. Set Post at intersection for corner Sec's. 3 & 4. 1) W. Pine 20" S68"W 15 L.; 2) Beech 6" S33"E 40 L. - 1930's – CCC Notes – T19N, R1E – South 80:00 Random post. 3rd mile post is 3.01'S and 1.35'E of random post. Post at Corner 33 & 34 is 1.70' E. and 1.20' S. of random. - 1963 – "Rivers Subdivision No. 1" – L. 9 of plats, P. 18 – Shows corner – H. J. Edmands - 1963 – "Rivers Subdivision No. 2" – L. 9 of plats, P. 20 – Shows corner – H. J. Edmands - 1974 – Record Survey L. 1, p. 407 – L. D. McGinnis – Fnd. Conc. Mon. 3) NNE 182.45' to Junct. Pole; 4) SSE 135.4' to P. Pole 5) E 44' to P. Line B. Description of corner evidence found and/or method applied in restoring or G1 – Closing comer common to Sections 3 & 4, T18N. R1E – Found Gladwin 'G13', T19N, R1E per Remonumentation LCRC – L. 1, p. 407. This post								Co. Remonumentation can an Constate Manuscrate										
L. 1, p. 406 and us should be two corn the concrete mon. witnesses at either Centerline of N-S preestablishment of	ners here 8 as a comn comer po powerline is	Link Ton o Sition S 47	s apart corner b Set 4 East a	t apout account of the count account a	pears epted R Alum	Rec. Sunthe that the lit only as n. Cap on e of Bit. R	vey by Mo 1930's Co the Star . 1" x 36"	COINNIS CC survidard C	vey r corne	ecover 'G	n 4. ered 13', T	Per to the s	tanda R1E	LO no ard co . No	otes a orner evide	at 'G	LO p 13'. I	lat there Rejected
C. Description of monum	nent for co	ner	and acc	essor	ies est	tablished	to perpet	uate lo	catin	ng the	e pos	ition	of the	corn	er:			
G1 – Stamped 4" DNR A East 1' to set Ceda West 5.28' to 'G13' N17°E 181.68' to s N88°E 88.49' to Fd S19°E 133.28' to F S22°W 5.19' to set	ar post. ', T18N, R et N & T ir I. nail in S. d. N & T ir	1E - Side	Gladwi side Pov 12" W. side Po	n Co. wer Po Pine wer P	Alum. ole								-			OF I	GW.	C. s.
Signed by: Surveyor's Michigan I	License No	1	10/	W/)/e_		Dar –	te:	1/2	6/	701	12	1	LICENS	S	No 390	88	F TON
	Social MC	***	_				_							Sala	PRO	FE SI	BION	The state of the s