

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in  
GLADWIN

(County)

Located In:

Corner Code ~~##~~

- |                                    |            |      |
|------------------------------------|------------|------|
| 1. Public Land Survey              | T 20N R 2E | B-10 |
|                                    | T R        | B-11 |
|                                    | T R        | C-10 |
|                                    | T R        | C-11 |
| 2. Property Controlling in Section | S T R      |      |
|                                    | S T R      |      |
| 3. Miscellaneous Property in Sec.  | S T R      |      |
|                                    | S T R      |      |

Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_
5. Private Claims \_\_\_\_\_

I, CARL T. KIISKILA, in a field survey on DECEMBER 8, 19 94, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

B-10

B-11

C-10

(NO EVIDENCE OF G.L.D. CORNER, B.T.'S, LINE TREES & TOPOGRAPHY, AS CALLED OUT IN THE G.L.D. LINE NOTES; UNLESS NOTED IN ITEM "B" BELOW.)

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	13		14		15		16		17		18		
7													
8	19		20		21		22		23		24		
9													
10	25		26		27		28		29		30		
11													
12	31		32		33		34		35		36		
13													



B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

B-10

B-11

C-10

C-11

ESTABLISHED THE CENTER OF SECTION 30 BY STANDARD PROCEDURE FOR SUBDIVISION OF A SECTION.

FOUND AND ACCEPTED A 1 1/4" PINCHED PIPE IN THE CTR OF E-W COUNTY ROAD FOR S 1/4 CORNER SECTION 30. COR FITS PLAT MON'S FD TO SE IN PLAT OF "WILDWOOD SHORES SUBDIVISION NO. 3" BY BERT REED, RLS #833, IN 1929. COR ALSO FD AND RECORDED BY L.McGINNIS, RLS #18999, IN 1977.

FOUND AND ACCEPTED A CAPPED 1/2" IRON IN CENTER ROAD. CORNER FITS CERTIFICATE SURVEYS IN SECTION 30.

FOUND AND ACCEPTED A 3/4" PIPE IN THE CENTER OF ROAD. CORNER FITS CERTIFICATE SURVEYS IN SECTION 30.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

B-10

B-11

C-10

C-11

SET DNR MON & CED POST.

FOUND PINCHED PIPE IN CTR E-W COUNTY RD.

FD CAPPED IRON IN CTR N-S ROAD #12" BASSWOOD N37°E 72.85' CTR DIVISION ST SOUTH 6.4' DIVISION ST SIGN POST

FD 3/4" PIPE IN CTR N-S ROAD.

6" MAPLE N84°W 31.98'  
20" W.PINE S09°W 14.43'  
6" MAPLE S68°E 25.68'  
9" SPRUCE N29°E 14.40'

POWER POLE N06°E 32.03'  
4" SQ CONC MON IN NE COR S04°W 32.91'  
4" W PINE S33°E 45.69'  
POWER POLE N79°E 105.9'

#POWER POLE S26°W 103.97'  
10" ASH N50°W 65.42'

#CTR OF RIVER LAKE RD TO EAST IS NORTH 54.5' RVR LK SIGN POST N29°E 79.9' #S END GUARD RAIL S20°W 59.22' #N END GUARD RAIL N40°E 35.33'

UPPER BLAZES AND SIDE NAILS.

\*OLD WITNESSES.

\* = P.LAPHAM, LS#9433, WIT.  
\*\* = L.McGINNIS, LS#1899, WIT.

Signed by Carl T. Kiiskila Date 1-23-96

Surveyor's Michigan License No. 33981