

**SURVEY &  
REMONUMENTATION**

**SEP 08 1998**

**SECTION**

**LAND CORNER RECORDATION CERTIFICATE**  
**Filing Requirement of Act 74, Mich. P.A. 1970**

For corners in

Gogebic  
(County)

Located In:

Corner Code =#

- |                                    |                           |             |
|------------------------------------|---------------------------|-------------|
| 1. Public Land Survey              | T <u>44N</u> R <u>39W</u> | <u>G-11</u> |
|                                    | T _____ R _____           | _____       |
|                                    | T _____ R _____           | _____       |
|                                    | T _____ R _____           | _____       |
| 2. Property Controlling in Section | S _____ T _____ R _____   | _____       |
|                                    | S _____ T _____ R _____   | _____       |
| 3. Miscellaneous Property in Sec.  | S _____ T _____ R _____   | _____       |
|                                    | S _____ T _____ R _____   | _____       |

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_
5. Private Claims \_\_\_\_\_

Section Corner 27, 28, 33 & 34; T.44 N., R.39 W.

Richard L. Drahn in a field survey on December 10, 19 97, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.**

A. Description of original monument and accessories and/or subsequent restoration:

Corner established by Wells Burt on 8/25/1851. Original B.T.s --- Y. Pine S.07 E. 74 links (48.84') --- Aspen 4" S.71 W. 9 links (5.94') ---

Corner restored by Donald D. Lappala (12585) on 5/23/61 from the scribed Red Pine stump. He set a 2" X 5" iron pipe with a 3" stamped cap and:

10"	Jack Pine	N.13½ E.	13.2'
7"	Jack Pine	N.60¼ E.	20.3'
9"	Jack Pine	S.39 W.	3.8'

Corner recorded in Gogebic County records in USFS Liber, Page V-13 on 8/29/62.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Corner research on file with Gogebic County records.

Recovered Lappalas' corner as described. His B.T.s have been destroyed by power line construction.

No evidence remains of the original bearing trees.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Bearing objects established by others but not on record:

10"	Jack Pine	N.87 E.	12.05'
12"	Red Pine	N.54 W.	100.41'
11"	Red Pine	N.08 E.	106.88'
6'	Steel sign post	East	2.74'

**PEER GROUP APPROVED**

Richard L. Drahn 12/19/97  
COUNTY REGISTRAR

igned by Richard L. Drahn

Date December 11, 1997

urveyor's Michigan License No. 21564

Register's Office }  
Gogebic County } ss.

Received for record the  
17<sup>TH</sup> day of MARCH  
A. D. 1998 at 9:50 o'clock  
A m., and recorded in  
Liber 6 of CORNERS  
on page 319  
Ramona Collins, Deputy  
Register of Deeds

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

