REMONUMENTATION

AUG 0 8 1997

COMMISSION

For corners in

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Cogabic	County	58.			
	Received	for	190	md	t
132	day	of.	MA	4	
A. D. 19	97_at	1:5	5-5	.o'cl	o.
P	m_,	and	reco	rded	
Liber 6	_	_oL	Cor	NE	R
on page.	102		,		
Pamo	na Coli	w	Do	рũ	t

Register's Office

Gogebic Located In: Corner Code ## T 45N R 45W 1. Public Land Survey R R 2. Property Controlling T R. in Section __ T _ _ R . Miscellaneous Τ... _ R _ S Property in Sec. R

Register of Deeds Stamp & File Number


Register of Doods

1.	Lot No, Recorded Plat
5.	Private Claims

Mile Corner No. 9, Mich .-- Wisc. State Line

I, Richard L. Drahn in a field survey on April 28, 19 97 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.



A. Description of original monument and accessories and/or subsequent restoration:

Corner established by William Burt in 1847. Original B.T.s --- Y. Birch 14" N.15 W. 26 links (17.16') --- Hemlock 18" S.13 E. 34 links (22.44') ---.

Corner restored by Earl G. Harrington in 1928 from the two original scribed bearing trees: the first was a 20" dead Hemlock at S.19-30 E., 22.4 feet; the second one was a 20" live Yellow Birch at N.08-30 W., 17.2 feet. He set a standard State Line concrete, brass capped monument and two new B.T.s:
--- Hemlock 14" S.58-30 E. 7.9 ft. --- Hemlock 12" N.41-45 W. 53.5 ft. ---

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Recovered the standard brass capped concrete monument as described in Earl Harringtons notes. His 1928 B.T.s are both now badly decayed Hemlock stumps at record bearing and distance.

William Burts 1847 B.T.s are as follows: live Yellow Birch w/GLO blazes and portions of scribing still visible at N.09 W. 22.4'. Tree is 26" dia.; the Hemlock B.T. is now a badly decayed stump, fragments of wood and bark are all that remain.

Research Form on file with Gogebic County records.

PEER GROUP AFFROYED

Ridord L. Drahm 5/12/97

COUNTY BURBERHATIVE

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

From the above described concrete monument I established the following new bearing objects:

9" Sugar Maple N.57 W. 34.28 feet

7" Yellow Birch N.68 E. 24.13 feet

11" Red Maple S.15 W. 18.96 feet

6" Steel sign rail N.06 E. 3.22 feet

USFS JK 10-11

aned by Richard L. Wzakn Date April 29, 1997

Surveyor's Michigan License No. 21564

RICHARD L. DRAHN

LAND SURVEYOR

> No. 21564

LAND