REMONUMENTATION

AUG 0 8 1997

COMMISSIUN

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

| Register's Office Conedic County | o e |
|-------------------------------------|-----|
| Gogebic County | 108 |

Received for record that

| For corners in | | • | 13 th day of MAY |
|--|---|--|---|
| Gogebic (County) | Located In: | Corner Code :/ ≠ | A. D. 1997 at 1:55 o'clock |
| 1. Public Land Survey | T45N R 45W T R T R/ | DE-5-6 # 004 | Pm, and recorded la Ulber 6 of Connex og page 103 Pamona Cours Deputy |
| 2. Property Controlling | S T R | | Register of Decemb |
| in Section | S T R | | |
| 3. Miscellaneous | S T R | | Register of Deeds Stamp & File Number |
| Property in Sec. | S T R | | |
| | ecorded Plat | | A B C D E F G H I J K L N |
| Mile Corner No | o. 8½, MichWisc | c. State Line | 3 |
| do hereby certify that under required lines 1 and 2 above were in current manual of survey instrument of the survey instrument of the survey of a above were in conformance with Court of Law; established, reexpressed below: | uirements of P.A. 74, Michigan P.J. conformance with regulations a ctions of the United States Depa Court of Law and/or that the corn the rules of the Michigan Board | A. of 1970, the corner points mention and rules therefore as required in artment of the Interior, Bureau of Liner points mentioned in lines 3, 4 at left Land Surveyors or by a Decree -monumented, recovered, found | oned 6 18 17 16 14 13 14 13 14 15 14 15 14 15 14 15 15 15 15 15 15 15 15 15 15 15 15 15 |

A. Description of original monument and accessories and/or subsequent restoration:

on this certificate.

Corner established by William Burt in 1847. Original B.T.s --- Sugar 12" S.53 W. 24 links (15.84') --- Y. Birch 16" N.09 E. 29 links (19.14') ---

Corner restored by Earl G. Harrington in 1928 from the scribed stump remains of the two original B.T.s. He set a standard State Line concrete, brass capped monument and two new B.T.s: --- Hemlock 10" S.08-30 W. 15.2 ft. --- Hemlock 8" N.25 W. 14.85 ft. ---

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Recovered the standard brass capped concrete monument as described in Earl G. Harringtons notes. His SW B.T. is now a decayed 12-16" Hemlock stump. His NW B.T. is now a decayed Hemlock windfall.

B.T. by Bill Stuth, Wisc. Surveyer is a scribed 16" Hemlock bearing N.09 E. 42.03' to a new nail in the side of the B.T.

1847 B.T.s by William Burt: --- Root holes with Y. Birch bark at N.09 E. 19.1' --- Shallow depression still remains at S.53 W. 15.8'. ----

Research Form on file with Gogebic County records.

Richard L. Drain 5/12/97
COUNTY BEPHESENTATIVE

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

From the above described concrete monument I established the following new bearing objects:

6" Sugar Maple N.02 W. 26.73 ft.

7" Sugar Maple S.83 E. 28.83 ft.

8" Sugar Maple S.83 W. 25.93 ft.

6' Steel sign rail N.20 E. 1.85 ft.

RICHARD
L. DRAHN
LAND
SURVEYOR
NO.
21564

Signed by Richard L. Drahn

Date <u>May 8, 1997</u>