

SURVEY &  
REMONUMENTATION

AUG 8 1997

COMMISSIONER

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

Register's Office }  
Gogebic County } ss.

Received for record the  
13<sup>TH</sup> day of MAY  
A. D. 1997 at 1:55 o'clock  
P m., and recorded in  
Liber 6 of CORNERS  
on page 104  
Ramona Collins Deputy  
Register of Deeds

Register of Deeds Stamp & File Number

For corners in

Gogebic  
(County)

Located In:

Corner Code ##

1. Public Land Survey

T 45N R 45W

CD-4-5

T R

T R

T R

T R

2. Property Controlling  
in Section

S T R

S T R

3. Miscellaneous  
Property in Sec.

S T R

S T R

4. Lot No. , Recorded Plat

5. Private Claims

Mile Corner No. 8, Mich.--Wisc. State Line

I, Richard L. Drahn in a field survey on May 4, 1997, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

Corner established by William Burt in 1847. Original B.T.s --- Sugar 14" N.43 E. (no dist.) --- Sugar 16" S.79 W. 9 links (5.94') ---

Corner restored by Earl G. Harrington from the stump of the original Sugar at S.79 W. 5.9 ft.. Stump was blazed and had measuring hack on it. He set a standard brass capped concrete monument and two new B.T.s --- Y. Birch 6" S.03-30 E., 15.8 ft. --- Hemlock 12" N.20-50 W., 20.1 ft.---

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Recovered the standard brass capped concrete monument as described in Earl G. Harringtons notes. His SE B.T. is now a series of root holes, species undetermined. His NW B.T. is now a 16-18" badly decayed Hemlock stump.

A shallow depression is all that remains of Burts SW B.T.

B.T.s by Bill Stuth, Wisc. Surveyor: --- 10" Sugar Maple S.16½ E. 14.24 ft. --- 9" Sugar Maple N.68 E. 23.62 ft.--- Trees scribed in 1984 on a survey by Stuth of portions of the Mich.--Wisc. State Line.

Research form on file with Gogebic County records.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

From the above described concrete monument I established the following new bearing objects:

8" Sugar Maple N.19 E. 13.37 ft.

6' Steel sign rail N.15 E. 2.08 ft.

PEER GROUP APPROVED

Richard L. Drahn 5/12/97  
COUNTY REPRESENTATIVE



Signed by Richard L. Drahn

Date May 8, 1997

Surveyor's Michigan License No. 21564