

COMMISSION

**LAND CORNER RECORDATION CERTIFICATE**  
**Filing Requirement of Act 74, Mich. P.A. 1970**

For corners in

Gogebic  
(County)

Located In:

Corner Code ~~##~~

1. Public Land Survey T 45N R 45W BC-4-5  
T \_\_\_\_\_ R \_\_\_\_\_  
T \_\_\_\_\_ R \_\_\_\_\_  
T \_\_\_\_\_ R \_\_\_\_\_
2. Property Controlling S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_  
in Section S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_  
\_\_\_\_\_
3. Miscellaneous S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_  
Property in Sec. S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_  
\_\_\_\_\_
4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_
5. Private Claims \_\_\_\_\_
- # 008

Mile Corner No. 7½, Mich.--Wisc. State Line

Richard L. Drahn, In a field survey on May 17, 1997, 19\_\_\_\_, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.**

A. Description of original monument and accessories and/or subsequent restoration:

Corner established by William Burt in 1847. Original B.T.s --- Cedar 12"  
S.26 E. 23 links (15.18') --- Spruce 10" N.05 W. 15 links (9.90') ---

Corner restored by Earl Harrington in 1928 from the scribed Cedar B.T. He set a standard brass capped concrete monument and one B.T.: Cedar 12" N.08-30 E., 11.35'.

Corner recovered by R. Drahn (21564) and J. Goss (23509) on 11/13/84. They recovered the concrete monument and Harringtons 1928 live Cedar B.T., with scribing visible. 1984 B.T.s 9" Cedar S.42 E. 21.00'; 6' rail North 1.8' B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

They recorded the corner in Gogebic County records in Liber 2, Pages 617-618 on December 6, 1984.

I recovered the corner monument as described above. The 1928 Cedar B.T. is still alive, with scribing visible and is 12" in dia. The 1984 Cedar B.T. is now dead and the 6' steel rail has been moved to N.12 E. 1.6'

Research form on file with Gogebic County records.

PEER GROUP APPROVED

Richard L. Drahn 6/10/97  
COUNTY REPRESENTATIVE

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

From the above described monument I established the following new B.T.s:

9" Cedar S.17 E. 23.09'

13" Cedar N.32 W. 26.55'

10" Cedar N.28 E. 9.25'

Signed by Richard L. Dralun

Date May 19, 1997

Surveyor's Michigan License No. 21564

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971  
REVISED MAY 14, 1975  
REVISED JAN., 1983

USFS HJ-4-5