	LAND CORNER RECORDATION CERTIFICATE				Gogebic County \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \								
	Filing Requirement of Act 74, Mich. P.A. 1970												
Fo	r corners in					16 1	, q	av e	f D	CCK	MB	EL	
	Gogebic	Located In:	Corner Code ##		A. D								
	(County)		}										
1.	Public Land Survey Se	ection 35 T <u>47N R 42</u> W.	J-13			P 4							
		T R R H2W	J-1		/	age		100	, [44	ر م	lbi	ty	
2.	Property Controlling	S T R						Regi	ster	.bf	Deed	8/	
	in Section	S T R				•					_		
3.	Miscellaneous	S R		Registe	r of D	eeds	Star	np &	File	Nur	nber		
	Property in Sec.	S T R											
4.	Lot No,	Recorded Plat			1 B	c b	ε	F G	н	1 7	к	L I	
5.	Private Claims			[Γ	Π	\sqcap		T 9		<u> </u>	
	One-quarter and T46N,	r corner common to S-35 & S R42W	S-2, T47N, R42W	3	— 6 —	5-			3	1		- -	
	wild 2 (VII)		vember 4 93	4	_{7-	- ∮	┿	6 —}	-10-	↓ _₁	5	-{2-	
۱, "	John R. Garske	in a field survey on	, 19	, 5			1	1		<u> </u>			
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the					—1 8	 		6	 15 	-	4	_ 3	
cu	rrent manual of survey inst	ructions of the United States Departr	nent of the Interior, Bureau of Lan	d 7		 - -	╫		_	+	\vdash		
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a					19	-20-		1-	2'2	2	3	24	
ab	ove were in conformance w	In the tuies of the Michigan Board of	cand Surveyors or by a Decree or convened found a	e 9		1 -		\vdash		┼	┞─┼		
Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:						—29-		8-	<u></u> 27	2	6	—25	

A. Description of original monument and accessories and/or subsequent restoration:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded

on this certificate.

Survey by William A. Burt, U.S.D.S., August 9, 1848. Set hemlock post from which a 8" cedar bears N50°E, 32 links and a 14" black ash bears N3°W, 42 links. No evidence found.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Corner was set by single proportion between monumented corners, set on line and half the distance between said monumented corners.

PEER GROUP APPROVED

Reclard L. Wrah 1/20/94

COUNTY REPRESENTATIVE

Register's Office

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set one section of 4' x 3/4" marsh rod with a 3 1/2" aluminum cap stamped: County Remonumentation; T47N, R42W; S-35; S-2; T46N; 1/4 cor.; 1993; RLS 28410. Established the following bearing trees and reference objects:

4" ash - N83°W - 13.64 feet 5" ash - N13°E - 16.30 feet 4" ash - S70°E - 17.07 feet Steel sign post - N26°W - 1.52 feet

Signed by R. Gardle

12/9/93

JOHN R.
GARSKE
LAND
SURVEYOR
NO.
28410

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SUBVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975

REVISED JAN., 1983