NOV 1 2 1997

COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Register'	s Office) County	~~
Gogebic	County)	53.
	Received	for

or corners in		
Gogebic (County)	Located In:	Corner Code ##
I. Public Land Survey	146N_R 46W	BC-13 001)
	T45N_R 46W	BC-1 013
	T R	
2. Property Controlling	S T R	
in Section	S T R	
3. Miscellaneous	S T R	
Property in Sec.	S T R	

Received for record the

9 TM day of October

A. D. 19 97 at 10:50 o'clock

A. m., and recorded in

Liber 6 of Coenses

Page 225

Remona Colims, Deputy

Register of Deeds

Register of Deeds Stamp & File Number

. Lot No, Recorded Plat

5. Private Claims .

State Closing Corner Sec's 31 & 6; T.45-46 N., R.46W. Line

Richard I. Drahn in a field survey on October 2. , 19 97 , do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

Corner established by John Burt on August 31, 1847. Original B.T.s --- Hemlock 22" N.49 E. 40 links (26.40') --- Y. Birch 18" N.49 W. 25 links (16.50') ---

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Restored corner position at record distance from Mile Corner No. ½ and record bearing and distance from the decayed remains of the two original bearing trees. The first is a series of root holes with fragments of Hemlock wood and bark. The second one is now a series of root holes with decayed fragments of Yellow Birch bark and wood.

Research form on file with Gogebic County records.

Richard R. Drahm 10/0/97
COUNTY REPRESENTATIVE

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

At the corner position I set a 2" X 30" aluminum pipe with a $3\frac{1}{4}$ " aluminum cap stamped to indicate the corner position and the following new B.T.s.

15"	Hemlock	S.28 W.	8.35'
14"	Hemlock	S.47 E.	30.30'
4"	Red Maple	s.70 E.	9.41'
6'	Steel sign rail	N.18 E.	1.97'
	A A	Α	

RICHARD
L. DRAHN
LAND
SURVEYOR
No.
21564

Signed by Richard L. Drahm

__ Date <u>__October_6, 1997</u>