

MAR 02 2000

SECTION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

Register's Office
Gogebic County

Received for record the

22ND day of OCTOBER

A. D. 1999 at 1:40 o'clock

P m., and recorded in

Liber 7 of CORNERS

on page 261

Ramona Collins Deputy
Register of Deeds

Register of Deeds Stamp & File Number

For corners in

Gogebic

(County)

Located in:

Corner Code #

1. Public Land Survey

T48N R46W

L-7

T R

T R

T R

T R

2. Property Controlling
in Section

S

T R

S

T R

3. Miscellaneous

S

T R

Property in Sec.

S

T R

4. Lot No. , Recorded Plat

5. Private Claims

Quarter corner, Sections 13 & 24, T48N, R46W

I, John P. Goss, in a field survey on Sept. 24 19 99 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

Corner established by Austin Burt, on May 23, 1851.

Original bearing trees: Sugar 20" S 52° E 10 links (6.60 ft.)

Y. Birch 20" N 36° W 20 links 13.20 ft.)

Richard L. Drahn, 21564, restored corner position at record bearing and distance from the windthrown stump holes of the original bearing trees and other record natural features and line trees. He set a 2" aluminum monument with 3/4" aluminum cap, stamped to indicated corner position. He established the following reference objects: 6" S. Maple - N 58° W - 21.89 ft.; 11" Y. Birch - N 55° E - 21.27 ft.; 11" Y. Birch - S 46° E - 25.38 ft.;

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

6" steel sign post - N 03° E - 1.6 ft.

He recorded said corner in Liber 2, page 703 of Land Corners, on 12-10-84

No original evidence found.

Found Richard L. Drahn, monument and accessories.

Act 74 research on file.

R. Drahn restored corner on July 30, 1984.

FREE GROUP APPROVED

Richard L. Drahn 10/14/99
COUNTY REGISTER

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

From the found monument I established the new and existing reference objects that follow:

99" Sugar Maple	N 58° W	21.89 ft.	
13" Yellow Birch	N 55° E	21.26 ft.	new nail
11" Yellow Birch (dead)	S 46° E	25.38 ft.	
7" Maple	S 18° E	21.70 ft.	
6" steel sign post	N 03° E	1.62 ft.	to face
(Measurement taken to nail in side of tree)			



Signed by John P. Goss

Surveyor's Michigan License No. 23509

USFS N-23

Date Sept. 24, 1999