

LAND CORNER RECORDATION CERTIFICATE
FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF-- LOCATED IN-- CORNER CODE NUMBER
1. PUBLIC LAND SURVEY T. 25 N. R. 10 W. I-11; K-11; J-11
2. PROPERTY CONTROLLING IN SECTION N. S. R. E. W.
3. MISCELLANEOUS PROPERTY IN SECTION N. S. R. E. W.
4. LOT NO. RECORDED PLAT
5. PRIVATE CLAIMS

REGISTER OF DEEDS STAMP AND
FILING NUMBER

I, CARL F. ROSER, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on September 14, 1983, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on , 19 , found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

C. CONTINUED:

XX

J-11
SET DNR MON & CEDAR POST
7" CEDAR N40°E 10.1'
8" CEDAR S25°E 11.9'
8" CEDAR S45°W 16.4'
CENTER CREEK (C-SOUTH) EAST 80'±

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:
I-11 FD LARGE POINTED STONE (VERTICAL) IN APPROX. CTR OF T-RD. INTER N-S-W; BURIED 4". STONE WAS RECOVERED BY E.H. ALLYN IN APRIL & SEPT. 1905 & SAID STONE WAS "SAID TO BE 2' LONG". WE CUT-CROSS IN TOP & SET HORSE SHOE ON TOP. COR. FN. POSTS (3 OF THEM) ARE 30'± EAST IN LINE WITH FENCE TO EAST.

K-11 FD OLD SHARP POINTED POST BOTTOM (4"X24"±) IN MUCK PER NORTHRUP (1896) AND E.P. WATERMAN (1907); BOTH OF WHOM HAD G.L.O. RE-SURVEY (1852) US BT'S. FITS DOUBLE ACROSS 1/8 CORNER & 1/4 CORNER TO NORTH.

J-11 RE-ESTAB. 1/4 COR TO SEC'S 26 & 35 EQUIDISTANT & ON LINE BETWEEN SEC. COR'S TO E & W. CORNER FALLS IN OLD E-W FN. (DOWN-IN SWP.).

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I-11
FD LARGE POINTED STONE ON END;
CUT CROSS & SET HORSE SHOE ON TOP
28" TWIN B. CHERRY N68°W 81.08'
10" RED PINE N20°W 80.13'
7" AUSTRIAN PINE N66°E 66.15'
42" MAPLE S16°E 132.15'
DISTANCES ARE TO ST. CUT SIDE NAILS
SET 5/8"X 36" RE-ROD W/RLS CAP N89°51'E 33.00'
SET CEDAR POST EAST 33'

K-11
SET DNR MON (ON 1"X36" PIPE)
OVER 1/2"X 36" PIPE (IN MUCK)
& CEDAR POST
5" CEDAR S80°W 18.2'
10" MAPLE S60°W 8.5'
20" WHITE PINE N25°W 45.6'

SIGNED BY Carl F. Roser 6/07/84

DATE

SURVEYOR'S MICHIGAN REGISTRATION NO. 12028

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY

DATE

CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY

DATE

MICHIGAN REGISTERED LAND SURVEYOR



(SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO.

GRAND TRAVERSE COUNTY