

LAND CORNER RECORDATION CERTIFICATE
FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF --:	LOCATED IN --:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY _____	T. <u>25</u> N. R. <u>11</u> W. ●	<u>L-9; L-10; L-11</u>
2. PROPERTY CONTROLLING IN SECTION <u>25</u>	T. <u>25</u> N. R. <u>11</u> W. ●	<u>15</u>
3. MISCELLANEOUS PROPERTY IN SECTION _____	T. _____ N. R. _____ E. W. ●	_____
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND
FILING NUMBER

I, Carl F. Roser do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram - over) were, in a field survey on April 29, 1974, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on 19, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

~~At Decree of Court of Law or by Decree of Michigan State Board of Registration for Land Surveyors and/or subsequent restoration~~
C. (continued)

15

Found wrecking bar added 1"x36" pipe
8" Twin Maple N40°W 41.60
7" Ironwood S53°W 50.50
12" B. Cherry N84°E 70.20
Ctr. E-W sand trail Due N 2'

- B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:
- L-9 Found 1" rod in intersection of county roads N-S-E-W. Fits survey of Sec. 25; Liber 5, pages 217-220, 1903.
- L-10 Recovered iron rod per old survey or record; Liber 5, pages 217-220, 1903.
- L-11 Found plow moldboard at intersection of dirt roads N-S-E-W. Fits survey of Sec. 25; Liber 5, pages 217-220, 1903.
- 15 Found wrecking bar in line with old fence to N. Fits survey of Sec. 25; Liber 5, pages 217-220, 1903.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

L-9	L-10	L-11
Drove 1"x18" pipe over found 1" rod	Found 3/4"x24" iron rod in center of N-S gravel road in line w/fence to E & W	Set 1"x36" pipe over plow moldboard
30" Maple S70°E 77.80	west ROW fence W 33.5	Corner fence post N55°W 45.10
30" Maple S22°E 119.70	east ROW fence E 31.6	24" B. Cherry N35°E 71.50
P. Pole S47°W 44.70	Set post w/loc. tag Due W 33'	8" Maple N64°E 76.60
		Set cedar post w/loc. tag S45°W 47'

SIGNED BY Carl F. Roser DATE 7-3-74

SURVEYOR'S MICHIGAN REGISTRATION NO. 12028

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____
MICHIGAN REGISTERED LAND SURVEYOR

(SEAL)

