## STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

## LAND CORNER RECORD

		_Gk	GRAND TRAVERED		COUNTY
		T .	36	<u> 1;</u>	R <u>0 W</u>
DESCRIPTION OF CORNER	Seation corner cormon	to Sections	28-29	-32-33	
CORNER MONUMENT	Set Std. Dept. Monumen	t	<del>.</del>	···•	
DATE MONUMENT PLACED AND	WITNESSED 8-31-70				
WITNESSES TO CORNER	7- Oak	N 45	T.		42.21
N	12" Oak	S 54	, 		90.61
2'6	Set Codar Guard Post	w/location	Tag i	Due S.	33'
	AND Corner in Centerline	E-W mand t	rail		
CIRCLE CORNER REGISTE	RED			<u> </u>	

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was recovered while making a retracement survey in this area. Schaaf notes show he had an original corner here. The USBTs, Y.Pine (stump) SW and W.Pine (stump remains) NE are still evident.

SURVEYOR'S SEAL

SIGNED

DECEMBED LAND SUBJETUDE

9-9-70

DISTRIBUTION:

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing