

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

<u>GRAND TRAVERSE</u> (County)	Located In:	Corner Code <u>77</u>
1. Public Land Survey	T <u>26N</u> R <u>09W</u>	<u>J-7</u>
	T <u> </u> R <u> </u>	<u> </u>
	T <u> </u> R <u> </u>	<u> </u>
	T <u> </u> R <u> </u>	<u> </u>
2. Property Controlling in Section	S <u>23</u> T <u>26N</u> R <u>09W</u>	<u>1</u>
	S <u>23</u> T <u>26N</u> R <u>09W</u>	<u>2</u>
3. Miscellaneous Property in Sec.	S <u> </u> T <u> </u> R <u> </u>	<u> </u>
	S <u> </u> T <u> </u> R <u> </u>	<u> </u>

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat
 5. Private Claims

I, CARL F. ROSER, in a field survey on MAY 5, 19 86.
 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

J-7 FD SCHAAF SQ CONC PIPE MON (2" LONG 1 1/2" DIA. PIPE IN SQ BLOCK OF CONC - NO MAG PULL ON OLD DIP NEEDLES) BURIED IN APPROX CTR OF E-W TRAIL RD (FIRE LANE). SCHAAF'S (1930'S) INDEX IN BACK OF CONSERVATION DEPT BROWN FIELD BOOK OF G.L.O. LINE NOTES (COPY) INDICATE SCHAAF HAD AN ORIG COR HERE. ROSER SET DEPT MON S.P. BETW SEC COR'S IN 1970 AS HE COULD NOT LOCATE SCHAAF MON THEN. IN 1985, RLS BOB MITCHELL FD SCHAAF MON. WE MOVED THE 1970 DEPT MON (1" X 36" PIPE-CAP BROKEN OFF) TO POSITION OF FD SCHAAF MON & REWITNESSED. OUR 1970 MON (MOVED) WAS N54°47'E 10.55' FROM FD SCHAAF MON.

1 RESET 1/8 COR TO MIDWAY & ON LINE BETW FD DEPT MON AT NW COR SEC 23 & FD M SCHAAF MON (REPLACED W/1" X 36" PIPE) AT N 1/4 COR SEC 23. CTR OF E-W SAND RD IS 3'±S. COR AS SET IN ERROR IN 1970 DEPT SUR (MOVED) WAS N63°38'E 6.60'.

2 RESET 1/8 COR TO MIDWAY & ON LINE BETW FD M SCHAAF MON. (REPLACED W/1" X 36" PIPE) AT N 1/4 COR SEC 23 & FD 1 1/4" PIPE AT NE COR SEC 23. COR AS SET IN ERROR IN 1970 DEPT SUR (MOVED) WAS N53°12'E 5.11'. *ctr of E-W trail road (Fire Lane) is centered over 1/8 Cor. ±.*

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

J-7		1	2
FD SCHAAF MON-REPLACED		DROVE 1" X 36" PIPE.	DROVE 1" X 36" PIPE.
W/1" X 36" PIPE.		18" OAK S28°W 112.1'	9" R PINE N36°E 59.2'
21" OAK N38°E 115.0'	16" OAK S54°W 87.4'	12" R PINE N70°E 69.7'	
17" OAK N36°W 115.6'	20" OAK N12°W 88.2'	6" W PINE N18°W 39.5'	
21" OAK S60°W 57.9'	SET CED POST	SET CED POST	
SET CED POST	W/LOC TAG. SOUTH 33'	W/LOC TAG. SOUTH 33'	
W/LOC TAG. NORTH 33'			

Signed by Carl F. Roser 4-30-87 Date
 Surveyor's Michigan License No. 12028

